

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name										The limited period of the SOP on this page is: 2023/7/27~~2023/10/27											
model				Process specific code		File No		Version production date		Farewell (small)		Pages (small)		Site (large) Page (large)							
NS5xx (except -E)		Check the back cover		Establish		1		IE 2470		Reference 1		2021/7/14		1		5-1/16		1		3-1/31	
B O M	NO.	Description	Parts Number		Q'TY 1	Torque	Remark		Quality Key Points/Precautions: 1. Wear an electrostatic bracelet during operation				Tools/Supplies: 1. Static electricity bracelet 2.Soft protective film 3. Protective film cutting jig								
	A back cover		BY S/O																		
Hold																					
do																					
explain																					
bright																					
1. Take the back cover (Ax) and check the appearance according to the standard. Cut a soft protective film of appropriate size and stick it on the back cover.																					
Note: 1. Check that the logo on the back cover must be pressed correctly, no words may be dropped, no words may be offset, and the neutral logo must be pasted correctly.																					
2. Press the logo back and forth 3 to 5 times, and peel off the protective film on the logo in parallel.																					
3. Paste a small protective film on the logo, and finally apply a soft protective film																					



1

model				Process specific	code	File No	Version	production date	Farewell (small)	Page (Small)	Site (Large)	Page (Large)	
NSSxx (except -E)		Lala glue		Establish	1	IE 2470	Reference 1	2021/7/14	1	5-2/16	1	3-2/31	
B O M	NO.	Description	Parts Number	Q'TY 2.1	Torque	Remark	Quality focus/precautions: 1. Wear an electrostatic bracelet during operation			Tools/Supplies: 1. Static electricity bracelet			
	A Lala glue		6-47-0019L-005/00A		FOR LCD:6-50/950-LXX46-XXX work (4.6)								
	B Lala glue		6-47-L1402-050	2.1	FOR LCD:6-50/950-LXX54-XXX work (5.4) Except LCD:6-50-LBB54-Y010/Z010/G010/Y011								
	C lala glue		6-47-L1402-050	2.1	For LCD 6-50-LBB50-Z010 6-50-LBB54-Z014/Z020 work								
	D Lala glue		6-47-0019L-006/00D	2.1	FOR LCD:6-50-LBB50-Z010 work								

Hold

do

explain



1. Stick the zip-up adhesive (A)*2 or (B)*2 or (C)*2 or (D)*2 on the back cover according to the marked line in the figure, and remove the zip-up adhesive backing.

Note: The rubber ears should be facing the Hinge.

bright

model				Process specific	code	File No	Version	production date	Farewell (small)	Page (Small)	Site (Large)	Page (Large)	
NS5xx (except -E)		Lala glue		Establish	1	IE 2470	Reference 1	2021/7/14	1	5-3/16	1	3-3/31	
B O M	NO.	Description	Parts Number	Q'TY	Torque	Remark	Quality focus/precautions: 1. Wear an electrostatic bracelet during operation				Tools/Supplies: 1. Static electricity bracelet		
	A	Lala gum	6-47-L1402-050	4.2	FOR LCD:6-50-LBB54- Y010/G010/Y011/G011/V011/Z011/Z020								

Hold

do

explain

bright

A1

左

四周断胶, 塑封不可

所有内孔注

允许

不可离

A2

A3

右

1.2 mA

0.8 mA

0.8 mA

允许反翘 0.2mm

2.844

0.66

0.75

8.1

A4

1. Stick the zip-up adhesive (A)*4 on the back cover according to the marked line in the figure, and remove the zip-up adhesive backing.

Note: Lala rubber ears facing outwards

1

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/27~~2023/10/27


model				Process specific	code	File number	version	production date		Farewell (small)	Page (Small)	Site (Large)	Page (Large)	
NS5xx (except -E)		Stick Rubber		Establish	1	IE-2470		Reference 1	2021/7/14	1	5-4/16		2	2-1/31
B O M	NO.	Description	Parts Number	Q'TY	2	Torque	Remark		Quality focus/precautions: 1. Wear an electrostatic bracelet during operation			Tools/Supplies: 1. Static electricity bracelet		
	A Rubber		6-47-NS501-040	2		FOR LCD:6-50/950-LXX46-XXX work (4.6)								
	B Rubber		6-47-NS501-031			FOR LCD:6-50/950-LXX54-XXX work (5.4)								
	C Rubber		6-47-NL501-011	2		FOR LCD:6-50-LBB54-Z013 work								
	D sponge		6-47-NS501-050	2		FOR LCD:6-50/950-LXX46-XXX work (4.6)								
	And Sponge		6-47-NS5P1-010-HM	2		FOR LCD:6-950/50-LBB46-Z020-XXy4.6y								
	F Rubber		6-47-NL401-051	2		FOR LCD:6-50-LBB54-Z012/Work								

Hold

do

explain


bright



- 1 As shown in the figure, attach Rubber (A)*2 or (B)*2 or (C)*2 to the position shown in the back cover or (F)*2 ---for manual attachment of the LCD.
- 2 As shown in the figure, attach sponge (D)*2 or (E)*2 to the position shown on the back cover.

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/27~~2023/10/27

model		Process specific code		File No		Version production date		Farewell (small)		Page (Small) Site (Large) Page (Large)	
NS5xx (except -E)		Stick Rubber		Establish 1		IE-2470		Reference 1 2021/7/14		1 5-5/16 2 2-2/31	
B O M	NO.	Description	Parts Number	Q'TY 2	Torque	Remark		Quality focus/precautions: 1. Wear an electrostatic bracelet during operation			
	A Rubber		6-47-NS501-031					Tools/Supplies: 1. Static electricity bracelet			
	B	Rubber	6-47-NL501-011	2		FOR LCD:6-50-LBB50-Z010/6-50-LBB54-Z013					
	C Rubber		6-47-NS701-010	2		FOR LCD:6-50-LBB54-V011					
	D Rubber		6-47-NL501-011	2		FOR LCD:6-50-LBB50-Z010					
	E Rubber		6-47-NS501-031	2		FOR LCD:6-50-LBB46-Z020					
Hold											
do											
explain											
bright	1 As shown in the figure, attach Rubber (A)*2 or (B)*2 or (C)*2 or (D)*2 or (E)*2 to the position shown on the back cover --- for manual attachment of the LCD.										


model				Process type	code	File No	Version	production date	Site type (small)	Page number (small)	Site type (large)	Page number (large)	
NS5xx (except -E)		Install CCD		Establish	1	IE-2470	Reference 1	2021/7/14	2		2-1/16	3	1-1/31
B O M	NO.	Description	Parts Number	Q'TY 1	Torque		Remark	Quality focus/precautions: By			Tools/Supplies: 1. Static electricity bracelet 2. Cable management stick		
	A1 CCD		6-88-NS50C-5110			S/O 1. Wear an electrostatic bracelet during							
	A2 CCD		6-88-NS50C-5101/5102	1		operation							
	B1 CCD cable		6-43-NS50T-011/021/010	1		By S/O By S/O							
	B2 CCD cable		6-43-NS5PT-010	1		By S/O							
	C sponge		6-47-NS501-050	1	FOR LCD:6-50/950-LXX46-XXX work (4.6)								
	D sponge		6-47-NS5P1-010-HM	1	FOR LCD:6-950/50-LBB46-Z020-XXy4.6y								

Hold



do

explain

bright



Pinch the iron shell here to get the CCD




Peel off the blue protective film

Plug the CCD cable into the CCD interface as shown in the figure



Peel off the adhesive on the CCD cable



- 1 Take the CCD as shown in the figure, take the CCD cable (B) and plug it into the CCD interface
2. Take the processed CCD, tear off the adhesive on the body, align and position the RIB, and install it on the back cover as shown in the picture.
3. Tear off the adhesive on the CCD cable and stick the CCD cable inside the MARK line on the back cover.
- 4 As shown in the figure, the CCD cable passes through the cable trough 1-hook 1-cable trough 2-hook 2-hook 3-hook 4
- 5 As shown in the figure, attach the sponge (C) and the position of the back cover as shown

model				Process code	file number	version	production date			Farewell (small)	Page (Small)	Site (Large)	Page (Large)	
NS5xx (except -E)		Check LCD		Establish	1		IE-2470	Reference 1	2021/7/14	2	2-2/16	4	1-1/31	
B O M	NO.	Description	Parts Number	Q'TY 1 1	Torque	Remark	Quality Key	Points/Notes: 1. Wear an electrostatic bracelet during work By S/O			Tools/Supplies: 1. Static electricity bracelet 2. Brushing the gun 3. Computer			
	A LCD		BY S/O	1										
	B1 LCD cable		6-43-NS501-011-S				By S/O							
	B2 LCD cable		6-43-NS501-011-1N				MIDERN							
	C Mylar		6-40-M55J2-030	1		Customer Import other now Customer BY M/O								

1 Take the LCD (A) and check the appearance according to the standard

Note: A. Tear off the LCD protective film and check whether the LCD is cracked

2. Take out the process card, swipe the barcode, and place the process card on the pallet.

3. Brush the LCD barcode and LCD light and dark points to enter the system.

4. For the Mofa back cover, swipe the back cover barcode (Cxxxxxxx) into the system

Note: When the Mofa back cover flows down with the thread, do not take it out from the non-woven bag. 5

Attach the LCD warranty sticker to the back of the LCD - the position is in the lower left corner

6. Attach the month mark to the back of the LCD - the position is to the lower left corner. Positive sticker

a. For customer Consign LCD, put "CONSIGN" sticker instead of monthly label

b. For trial production models, this monthly label does not need to be attached.

7 Take the LCD cable (B) and insert it into the LCD interface (the LCD cable must be inserted all the way)

8. Tear off the adhesive tape on the cable tie and stick it on the LCD.

9 Attach 1pcs mylar (C) on the back at the position shown in the picture above

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name


The limited period of the SOP on this page is: 2023/7/27~~2023/10/27

model			Process code	file number	version	production date		Farewell (small)	Page (Small)	Site (Large)	Page (Large)	
NS5xx (except -E)		Install LCD on the back cover		Establish	1	IE-2470 Part 1		2021/7/14	3	2-1/16	5	1-1/31
B O M	NO.	Description	Parts Number	Q'TY	Torque Remark	quality points/notes	1. Wear an electrostatic bracelet during operation			Tools/Supplies: 1. Static electricity bracelet 2. Cable management stick		

Hold

do

explain



- 1 Install the LCD on the back cover along the upper left corner of the back cover as shown in the figure
- 2 Press the adhesive position on the back cover to make the LCD and back cover stick better
3. As shown in the figure, arrange the LCD cable through the cable trough 1-hook 1-cable trough 2-hook 2-hook 3-hook 4
- Note: For LCD cable 6-43-NS501-011-1N/S: Fold the LCD cable interface conductive cloth in half according to the arrow in the figure.

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/27~~2023/10/27


model				Process code	file number	version	production date		Site (small)	Page (small)	Site (large)	Page (large)	
NS5xx (except -E)		Install Hinge on the back cover		Establish	1		IE-2470 Part 1		2021/7/14	3	2-2/16	6	1-1/31
B O M	NO.	Description	Parts Number	Q'TY 1	Torque		Remark	quality focus/notes: Tools/consumables:			Electric driver, self-supplied screw machine		
	A Hinge-L		6-33-NS501-0L1					1. Wear an electrostatic bracelet during work 1. Electrostatic bracelet					
	B Hinge-R		6-33-NS501-0R1	1				2. The hanging height of the fixture (i.e.: pallet y height of the lowest point of the fixture) y 38 cm 2					
	C screw		6-35-B6120-3RD	4	1.5±0.2			3. Lock the screws in order, and be careful not to slip or miss the lock.					
	D Sponge		6-47-0019A-00H	1			BY M/O						

Hold

do

explain

bright



- 1
- Take Hinge-L (A) & Hinge-R (B) and align the positioning posts and install them on the back cover
2. Take a total of 4 screws (C1~C4) to lock the Hinge on the back cover (the one with a triangle symbol on the body)
- Note: LCD & CCD cables are not free of hinges
- 3 Paste Sponge (D)*1 as shown in the picture


model		Process type	code	File number version	production date		Farewell (small)	Page (Small) Site (Large)	Page (Large)	
NS5xx (except -E)	Install HINGE CAP on the back cover	Establish	1	IE-2470	Reference 1	2021/7/14	4	3-1/16	7	1-1/31
B O M	NO.	Description	Parts Number	Q'TY 1 2	Torque	Remark quality focus/notes: Tools/consumables:				
	A HINGE CAP		6-42-NS501-102							
	B screw		6-35-82125-4R5/-1		2.5±0.2	1. Wear an electrostatic bracelet during work 1. Electrostatic bracelet 2. The hanging height of the fixture (i.e.: pallet y height of the lowest point of the fixture) y 38 cm 2. Electric driver, self-supplied screw machine 3. Lock the screws in order, and be careful not to slip or miss the lock.				

Hold

do

explain

bright



- 1 Take HINGE CAP (A) and check the appearance according to the standard
- 2 Install the HINGE CAP on the back cover and engage the hooks shown in the Hinge icon on both sides.
- 3 Follow the sequence shown in the figure and press HINGE CAP manually
- 4 Take out the screws (B)*2 and lock the HINGE GAP as shown in the figure
- 5 Pull all the wires at the left hinge back and forth 2 to 3 times, and check that the front and rear covers are combined with the left hinge so that no wires are caught.

model				Process type	code	File number version	production date	Farewell (small)	Page (Small) Site (Large) Page (Large)	
NS5xx (except -E)		Card front frame		Establish	1	IE-2470	Reference 1 2021/7/14	4	3-2/16	8 1-1/31
B O M	NO.	Description	Parts Number	Q'TY 1 1	Torque	Remark quality points/notes: 1. Wear an electrostatic bracelet during work	Tools/Supplies: 1. Static electricity bracelet			
		A Front frame B1	BY S/O							
		CCD LENS B2 CCD LENS	6-42-NS501-050							
			6-42-NS501-060	1						

Hold

do

explain



1 Take the front frame (A) and check the appearance according to the standard

Note: If the front frame comes with its own adhesive, remove the adhesive.

2 Tear off the LCD protective film and install the front frame (A) on the back cover

3 Follow the sequence shown in the figure and press the front frame manually

4 Put back the LCD protective film

5 Take the CCD Lens (B) and install it on the front frame with the tail facing right

Note: The small blue Mylar on the CCD Lens cannot be removed.

bright

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name



The limited period of the SOP on this page is: 2023/7/27~~2023/10/27

model		Process type	code	File number version	production date	Farewell (small)	Page (Small)	Site (Large)	Page (Large)	
NS5xx (except -E)	Install HINGE CAP on the back cover	Establish	1	IE-2470	Reference 1 2021/7/14	4	3-3/16	9	1-1/31	
B O M	NO.	Description	Parts Number	Q'TY 5	Torque	Remark quality focus/notes: Tools/consumables: 1. Wear an electrostatic bracelet during work 1. Electrostatic bracelet 2. The hanging height of the fixture (i.e.: pallet y height of the lowest point of the fixture) y 38 cm 2. Electric driver, self-supplied screw machine 3. Lock the screws in order, and be careful not to slip or miss the lock.				
	A screw		6-35-82125-4R5/-1		2.5±0.2					

Hold


do

explain



1 Take out the screws (A)*5 and lock the HINGE GAP as shown in the figure

bright

model			Process specific code		File number version production date			Farewell (small)	Page (Small) Site (Large) Page (Large)			
NS5xx (except -E)		Post Mylar		Establish	1	IE-2470	Reference 1	2021/7/14	5	3-1/16	10	1-1/31
B O M	NO.	Description	Parts Number	Q'TY	Torque	Remark	Quality focus/precautions: 1. Wear an electrostatic bracelet during operation			Tools/Supplies: 1. Static electricity bracelet 2. Plastic tweezers		
	A Mylar		6-40-NS501-050/051	7.2								
Hold												
do												
explain												
1. Take Mylar (A)*7 and stick it on the front frame as shown in the picture with plastic tweezers.												
bright												

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/27~~2023/10/27



model				Process specific code	File number	version	production date		Farewell (small)	Page (Small)	Site (Large)	Page (Large)	
NS5xx (except -E)		Processing TP		Establish	1	IE-2470	Reference 1	2021/7/14	5	3-2/16	11	1-1/31	
B O M	NO.	Description	Parts Number	Q'TY 1	Torque	Remark	Quality focus/precautions: W/			Tools/Supplies:			
	A1 T/P		6-49-NL4C3-011			FP 1. Wear an electrostatic bracelet during	W/O FP 2. Pressing time: W/ FP 3. Fixture pressure: 5.9-6.9kgf/cm³			1. Static electricity bracelet 2.NS50MU TP iron fitting fixture/01 3.NS50MU TP iron assembly jig 4.Click PAD iron parts laminating machine			
	A2 T/P		6-49-NL403-011			operation W/O							
	A3 CLICK PAD ELAN		6-49-NS503-010/011			10s W/ FP							
	A4 CLICK PAD ELAN		6-49-V15K3-011	1 1 1		W/O FP BY							
	B	Click PAD BKT		6-33-NS502-011/012/013	1								

Hold

do

explain

bright




1. Take TP (Ax) as shown in the figure and place it in the iron fitting jig.

Remarks: Laminating jig number: NS50MU TP iron fitting jig/01

- 2 Take Click PAD BKT (B), tear off its release paper, and place it in the iron attachment jig as shown in the picture.

- 3 Place the processed Click PAD in the iron pressing jig for pressing

Remarks: Pressing fixture number: NS50MU TP iron parts pressing fixture

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name												The limited period of the SOP on this page is: 2023/7/27~~2023/10/27									
model					Process specific code		File number version production date			Farewell (small)		Page (Small) Site (Large) Page (Large)									
NS5xx (except -E)		Check the upper cover			Establish		1		IE-2470		Reference 1	2021/7/14		5		3-3/16		12		1-1/31	
B O M	NO.	Description		Parts Number		Q'TY 1		Torque		Remark		Quality focus/precautions: 1. Wear an electrostatic bracelet during operation					Tools/Supplies: 1. Static electricity bracelet				
	A Upper cover				BY S/O																
Hold																					
do																					
explain																					
bright																					
A Take out the upper cover from the raw material outer box (A) and check the appearance according to the standard																					


1

model				Process specific code	File number version production date			Farewell (small)	Page (Small) Site (Large) Page (Large)			
NS5xx (except -E)		Install T/P		Establish	1	IE-2470	Reference 1	2021/7/14	6	4-1/16	13	1-1/31
B O M	NO.	Description	Parts Number	Q'TY 3	Torque	Remark	Quality Focus/Notes: Tools/Supplies:					
	A screw		6-35-B1120-2RA/-1		1.5±0.2	W/ FP 1. Wear an electrostatic bracelet during work 1. Electrostatic bracelet						
						2. The hanging height of the fixture (i.e.: pallet y height of the lowest point of the fixture) y 38 cm 2. Electric driver, self-supplied screw machine						
						3. Lock the screws in order, and be careful not to slip or miss the lock.						

Hold

do

explain



- 1 Take the processed TP and assemble it with the upper cover as shown in the figure
- 2. Take the screws (A)*3 and fasten the TP to the upper cover in the order shown in the picture.
- 3. Peel off the black Mylar release paper that comes with the incoming material and stick it on the TP.

bright



model				Process specific code		File number version		production date		Farewell (small)		Page (Small) Site (Large) Page (Large)									
NS5xx (except -E)		Processing TP Mylar		Establish		1		IE-2470		Reference 1		2021/7/14		6		4-2/16		14		2-1/31	
B O M	NO.	Description	Parts Number	Q'TY 1	Torque	Remark		Quality focus/precautions: 1. Wear an electrostatic bracelet during operation 2. Pressure range: 5.9~6.9Mpa 3. Pressing time: 5S					Tools/Supplies: 1. Static electricity bracelet 2. Name of pressing fixture:								
	A1 TP MYLAR		BY S/O																		

Hold

do

explain

bright



1. Take TP Mylar (A) and put it into the location shown in the device icon.
- 2 Take the TP Mylar laminating jig and put it into the equipment
- 3 Press the green start button to start the device
- 4 Wait for the device to automatically attach TP Mylar and laminate TP Mylar
- 5 Remove the upper cover and check whether the TP Mylar is centered, skewed, etc.

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name											The limited period of the SOP on this page is: 2023/7/27~~2023/10/27											
model					Process specific code		File number version		production date		Farewell (small)		Page (Small) Site (Large) Page (Large)									
NS5xx (except -E)		Processing TP Mylar			Establish		1		IE-2470		Reference 1	2021/7/14		6		4-3/16		14		2-2/31		
B O M	NO.	Description		Parts Number		Q'TY 1		Torque		Remark		Quality focus/precautions: 1. Wear an electrostatic bracelet during operation 2. Fixture pressing time: 5s 3. Fixture pressure: 5.9~6.9kgf/cm³					Tools/Supplies: 1. Static electricity bracelet 2.NS50MU TP Mylar laminating fixture					
	A TP MYLAR				BY S/O																	
Hold																						
For work when taking out fingerprints																						
Align top edge for attachment Ax																						
do																						
explain																						
1. Take TP mylar (Ax) and extend the upper edge and stick it to the position shown in the picture. 2 Place the cover in the TP laminating jig 3 Press the start button to press																						
Note: When taking out fingerprints, TP Mylar needs to be attached manually.																						
bright																						

NS50MU TP Mylar laminating fixture

1



model					Process specific code		File number version		production date		Farewell (small)		Page (Small)		Site (Large)		Page (Large)					
NS5xx (except -E)		yCLICK SWITCH BKT			Establish		1		IE-2470		Reference 1		2021/7/14		6		4-4/16		15		1-1/31	
B O M	NO.	Description	Parts Number	Q'TY 1 3	Torque	Remark	Quality Focus/Notes: Tools/Supplies:															
	A CLICK	SWITCH BKT 6-33-NS502-031/013					1. Wear an electrostatic bracelet during work 1. Electrostatic bracelet															
	B screw		6-35-B1120-3RD		1.5±0.2		2. The hanging height of the fixture (i.e.: pallet y height of the lowest point of the fixture) y 38 cm 2. Electric driver, self-supplied screw machine															
							3. Lock the screws in order, and be careful not to slip or miss the lock.															
Hold																						
do																						
explain																						
bright																						
1 Take CLICK SWITCH BKT (A) and install it at the position shown in the upper cover																						
2. Take the screws (B)*3 and lock the iron parts on the upper cover in the order shown in the picture.																						
1																						

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/27~~2023/10/27

model				Process code	file number	version	production date				Farewell (small)	Page (Small)	Site (Large)	Page (Large)	
NS5xx (except -E)		The upper cover is combined with the LCD part			Establish	1	IE-2470 Part 1		2021/7/14		7	2-1/16	16	1-1/31	
B O M	NO.	Description A	Parts Number	Q'TY 4	Torque	Remark quality	points/notes: 1. Wear an electrostatic bracelet during work 2. Fixture hanging height (i.e.: pallet y height of the lowest point of the fixture) y38 cm 2. Electric screwdriver, self-supplied screw machine 3. Lock the screws in order, be careful not to slip or miss the lock 3. Soft protective film					Tools/Supplies: 1. Static electricity bracelet 2. Electric screwdriver, self-supplied screw machine 4. Protective film cutting jig			
	screw		6-35-82125-6RA/-1		2.5±0.2										
	B1 Upper cover		6-78-NS50MU02-01x/02x	1		BY SO									
	B2 Upper cover		6-78-NS50MU02-01x/02x-xx	1		BY SO									
	B3 Upper cover		6-78-NS50MU02-010/011/020/021/-xx	1		BY SO									
	B4 Upper cover		6-78-NS51MU02-010/011/020/021-xx	1		BY SO									
Hold	B5 Upper cover		6-78-NS50PU02-010/011/020/-xx	1		BY SO									
	B6 Upper cover		6-78-NS51PUHM2-010	1		BY SO									
	B7 Upper cover		6-78-NS50AU02-001	1		BY SO									
do															
explain 1 Take the upper cover (Bx), remove the packaging bag, check the appearance, cut a suitable size of soft protective film and stick it on the upper cover 2. Take the upper cover (B) and combine it with the LCD part. Take 4 screws (A1~A4) to lock the Hinge (the one with the triangle symbol on the body) Note: The upper cover screw holes and Hinge screw holes must be aligned															
bright															

KAPOK Standard Operation PROCEDURE

Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/27~~2023/10/27


model			Process code	file number	version	production date			Farewell (small)	Page (Small)	Site (Large)	Page (Large)	
NS5xx (except -E)		Install HALL SENSOR small card	Establish		1	IE-2470 Part 1		2021/7/14	7	2-2/16	17	1-1/31	
B O M	NO.	Description	Parts Number	Q'TY	1	1	Remark	quality	Focus/notes: Tools/consumables: 1. Wear an electrostatic bracelet during work 1. Electrostatic bracelet 2. The hanging height of the fixture (i.e.: pallet y height of the lowest point of the fixture) y 38 cm 2. Electric driver, self-supplied screw machine 3. Lock the screws in order, and be careful not to slip or miss the lock.				
	A1	HALL SENSOR small card 6-77-NS501-D02/D03											
	A2	HALL SENSOR small card 6-77-NS5A1-D01											
	B	LID TO MB cable	6-43-NS500-031/-1										
	C	screw	6-35-1-B1120-4RC/-1	1	1		1.5±0.2						

Hold

do

explain

bright



1. Take the HALL SENSOR small card (A), open the HALL SENSOR small card interface baffle, take the cable (B) with the word LID on one end and insert it into the corresponding interface of the small card, and snap the baffle to fix the cable.
2. Take the processed HALL SENSOR small card and install it on the upper cover as shown in the picture, and take out the screw (C)*1 to lock it.
3. Tear off the adhesive tape of the cable and stick it on the upper cover.

model				Process code	file number	version	production date	Site (small) Page (small) Site (large) Page (large)			
NS5xx (except -E)		Install Wlan antenna		Establish	1		IE-2470 Part 1	8	3-1/16	18	2-1/31
B O M	NO.	Description A	Parts Number	Q'TY 1 1	Torque	Remark quality points/notes: 1. Wear an electrostatic bracelet during work					
	Wlan-1 antenna B Wlan-2		6-23-7NS50-010								
	antenna		6-23-7NS50-020								


This site has 2 pages in total, this is page 1

Hold

do

explain

bright



1. Tear off the adhesive on the Wlan-2 antenna (B) body and install it on the upper cover as shown.
 2. Peel off the adhesive backing of copper foil 2 and stick copper foil 2 vertically on the upper cover
 - 3 As shown in Figure 1, check Wlan-2 antenna hook 1
 4. Tear off the adhesive on the Wlan-1 antenna (A) body, as shown on the upper cover.
 5. Peel off the adhesive backing of copper foil 1 and stick copper foil 1 vertically on the upper cover.
- Note 1. Copper foil 1&2 need to be attached under the mylar on the upper cover, and copper foil 1 needs to press the Wlan-2 antenna
2. Tear off the blue Mylar release paper that comes with the incoming material, and stick the black Mylar on the copper foil.
- 6 As shown in the figure, the WLAN-1&Wlan-2 antenna passes through hook 2-hook 3-hook 4

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/27~~2023/10/27





model				Process code	file number	version	production date		Site (small)	Page (small)	Site (large)	Page (large)	
NS5xx (except -E)		Install Wlan antenna		Establish	1		IE-2470 Part 1		2021/7/14	8	3-2/16	18	2-2/31
B O M	NO.	Description A	Parts Number	Q'TY 1 1	Torque	Remark	quality	points/notes: 1. Wear an electrostatic bracelet during work				Tools/Supplies: 1. Static electricity bracelet 2. Cable management stick	
	Wlan-1 antenna	B Wlan-2	6-23-7NS5P-010										
	antenna		6-23-7NS50-020										

Hold

do

explain

bright



1. Tear off the adhesive on the Wlan-2 antenna (B) body and install it on the upper cover as shown.
 2. Peel off the adhesive backing of copper foil 2 and stick copper foil 2 vertically on the upper cover
 - 3 As shown in the figure, the Wlan-2 antenna passes through hook 1-hook 2-hook 3
 4. Tear off the adhesive on the Wlan-1 antenna (A) body, as shown on the upper cover.
- Pay attention to tear off the Mylar blue release paper that comes with the incoming material, and stick the black Mylar on the copper foil.
- 5 As shown in Figure Wlan-2 antenna

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/27~~2023/10/27

model				Process code	file number	version	production date			Farewell (small)	Page (Small)	Site (Large)	Page (Large)	
NS5xx (except -E)		Manage CCD cables		Establish		1	IE-2470 Part 1		2021/7/14	8	3-3/16	19	1-1/31	
B O M	NO.	Description A	Parts Number	Q'TY 1	Torque									
		Mylar B washer	6-40-W25P3-010											
			6-37-02000-601	1										




points/notes: 1. Wear an electrostatic bracelet during work

- Tools/Supplies:
- 1. Static electricity bracelet
 - 2. Cable management stick
 - 3. CCD cable management fixture: NS50-QT01-1003-01

Hold

do

explain



- 1 Use the jig to arrange the CCD cable & 3G-1 antenna through hook 1-hook 2-hook 3-cable trough 1-hook 4
- 2 As shown in the figure, attach Mylar (A) to fix the CCD cable
3. Attach Washer (B) to the position shown on the upper cover as shown in the picture.

Note: There is no washer attached to the lower cover 6-39-NS503-013/014.

bright

model			Process code	file number	version	production date			Site (small) Page (small)	Site (large) Page (large)		
NS5xx (except -E)		Locking the motherboard	Establish	1		IE-2470 Part 1		2021/7/14	9	2-1/16	20	1-1/31
B O M	NO.	Description	Parts Number	Q'TY 1 1	Torque	Remark quality	Focus/notes: Tools/consumables:					
		A Mainboard B1	6-77-NS5xxx-xxx-xx				1. Wear an electrostatic bracelet during work 1. Electrostatic bracelet					
		MULTI BOARD B2 MULTI BOARD C	6-77-NS507-D03				2. The hanging height of the fixture (i.e.: pallet y height of the lowest point of the fixture) y 38 cm 2					
		Screws	6-77-NS5A7-D01	1			3. Lock the screws in order, and be careful not to slip or miss the lock.					
			6-35-B6120-2RE	3	2.0±0.2							

Hold

do

explain

bright

1 Take out the motherboard (Ax) and check the motherboard material number and version

2 Install the motherboard on the upper cover

Note: When installing the motherboard, do not press the LCD cable, CCD cable, or Wian antenna.

3 Take out the screws (C)*2 to fix the motherboard to the upper cover

4 Take the MULTI card and install it on the upper cover as shown in the picture, and secure it with screw (C)*1

5 Plug the CCD cable into the motherboard interface

1


1 Take the iron piece (B) and install it at the position shown in the picture, and tighten the screws (A)*4 to fix it

model			Process code	file number	version	production date		Site (small) Page (small)	Site (large) Page (large)		
NSSxx (except -E)		Plug in the cable	Establish	1	IE-2470 Part 1		2021/7/14	10	2-1/16	22	1-1/31
B O M	NO.	Description	A USB1	Parts Number	Q'TY 1	Torque	Remark	quality points/notes: 1. Wear an electrostatic bracelet during work	Tools/Supplies: 1. Static electricity bracelet		
		TO MB cable 6-43-NS500-041/-1 B USB1 TO MB cable 6-43-NS500-051/-1 C Screw									
		6-35-1-B1120-4RC/-1		1							
				1	1.5±0.2						

Hold

do

explain



1. Take the USB cable (A) & (B) and insert the USB cable into the small card interface. Tear off the mylar adhesive tape to fix the cable.
2. Tear off the adhesive on the bottom of the USB cable, stick it on the upper cover, insert the USB cable into the MB interface, and remove the mylar adhesive on the cable to secure the cable.
3. Organize the battery cable hook 2 as shown in the figure, remove the COMS battery backing tape and stick it in the battery slot.
4. Take the screw (C)*1 to fix the motherboard to the upper cover.

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/27~~2023/10/27



model		Process code		file number	version	production date	Site (small) Page (small)		Site (large) Page (large)		
NS5xx (except -E)		Plug in the cable		Establish	1	IE-2470 Part 1	10		2-2/16	23	2-1/31
B O M	NO.	Description A1	Parts Number	Q'TY 1	Torque	Remark quality focus/notes: WO/FP 1. Wear an electrostatic bracelet W/FP during operation	Tools/Supplies: 1. Static electricity bracelet				
	Click cable	A2 Click cable	6-43-NS500-010/-1								
	B FP cable		6-43-NS500-020/-1	1							
			6-43-NS500-060/-1	1		W/FP					

Hold

do

explain

bright




1. Open the interface baffle on the T/P, insert the Click cable (A) with the word CK on the interface, snap the baffle to fix the cable, peel off the adhesive at the bottom of the Click cable, and stick it to the upper cover
- 2 Plug the Click cable into the MB interface
- 3 W/FP---Open the interface baffle on the T/P, insert the FP cable (B) with the word FP on the interface, snap the baffle to fix the cable, peel off the adhesive on the bottom of the FP cable, and stick on top
- 4 W/FP---Plug the FP cable into the motherboard interface

model				Process code	file number	version	production date			Farewell (small)	Page (Small)	Site (Large)	Page (Large)	
NS5xx (except -E)		yFAN + HEAT SINK		Establish		1	IE-2470	Reference 1	2021/7/14	11	3-1/16	23	2-2/31	
B O M	NO.	Description	A1 FAN	Parts Number	Q'TY	1	Torque	Remark quality points/notes: 1. Wear an electrostatic bracelet during work				Tools/Supplies: 1. Static electricity bracelet		
		+ HEATSINK	6-31-NS502-102/103/-1/-1A	A2 FAN + HEATSINK	6-31-NS5PN-101									
						1								

Hold

do



a.FAN cable arrangement should be arranged to the left first.

b. FAN cable and then fold it to the right for cable management

c.Tear off the Mylar adhesive that comes with the incoming material Fixed FAN cable)

explain

bright

1 Install FAN + HEATSINK (A) on the top cover as shown in the picture

Note: When installing FAN + HEATSINK, do not press the Mylar & Wlan antenna shown in the picture.

2. Remove the Mylar adhesive that comes with the incoming material and fix the Wlan antenna as shown in the figure.

3 Insert the FAN cable into the position shown on the motherboard and arrange the cable according to the steps shown in the picture

4. Tear off the Mylar adhesive that comes with the incoming material to fix the FAN cable.

Note: The new lower cover 6-39-NS503-014 must be used with HEATSINK: 6-31-NS502-103/-1

1

Review check: Qian Lin

Written by:Song Zhiheng


model				Process code	file number	version	production date			Site (small) Page (small)	Site (large) Page (large)		
NS5xx (except -E)		FAN + HEATSINK		Establish		1	IE-2470 Part 1		2021/7/14	11	3-2/16	24	2-1/31
B O M	NO.	Description A	Parts Number	Q'TY 7	Torque	Remark quality focus/notes: Tools/consumables:							
	screw		6-35-B1120-4RC/-1		1.5±0.2	1. Wear an electrostatic bracelet during work 1. Electrostatic bracelet 2. The hanging height of the fixture (i.e.: pallet y height of the lowest point of the fixture) y 38 cm 2 3. Lock the screws in order, and be careful not to slip or miss the lock.							

Hold

do

explain

bright



1 Take out the screws (A)*7 and lock the HEATSINK in order

1



model				Process code	file number	version	production date			Site (small) Page (small)	Site (large) Page (large)		
NS5xx (except -E)		YFAN + HEATSINK		Establish		1	IE-2470 Part 1		2021/7/14	11	3-3/16	24	2-2/31
B O M	NO.	Description A	Parts Number	Q'TY 2	an	Remark quality	focus/notes: Torque 1. Wear electrostatic bracelet FOR NS5XPU AU/-xx during operation. Tools/Supplies: 1. Static electricity bracelet						
	Mylar		6-40-M55J2-030										

Hold



do




explain

bright



1. As shown in the figure, pass the LCD cable through hook 1-hook 2, and insert the LCD cable into the motherboard interface.
- 2 Take the WLAN-1 antenna as shown in Figure and fix it with Mylar (A)*2



model				Process code	file number	version	production date			Farewell (small)	Page (Small)	Site (Large)	Page (Large)																																													
NS5xx (except -E)		Install Wlan card		Establish	1		IE-2470	Reference 1	2021/7/14	12	3-1/16	25	2-1/31																																													
B O M	NO.	Description A1	Parts Number	Q'TY 1	Torque	Remark quality focus/notes:				Tools/Supplies:																																																
	WLAN card		6-88/998-N15CF-4210/-W			BY S/O 1. Wear an electrostatic bracelet during work 1. Electrostatic bracelet				Self-supplied screw machine																																																
	A2 WLAN card		6-88-NV40F-4210			BY S/O 2. Fixture hanging height (i.e.: pallet y height of the lowest point of the fixture) y38 cm 2. Electric driver,																																																				
	A3 WLAN card		6-88/988-N24GF-4200/-HL			BY S/O 3. Lock the screws in order, be careful not to slip or miss the lock.																																																				
	A4 WLAN card		6-988-NV40F/L140F-4210-HL			BY S/O																																																				
	A5 WLAN card		6-88/988-X270F-4210/-HL	1 1 1 1		BY S/O																																																				
	A6 WLAN card		6-88-NL5RF-7000	1		BY S/O																																																				
	B screw C Mylar		6-35-Z9120-3R2	1	1.5±0.2	Standard configuration																																																				
		6-40-M55J2-030	1																																																							
Hold	 <table><tr><th colspan="4">Wlan天線對應Wlan卡接口區分方式</th></tr><tr><th>天線</th><th>Wlan-1天線</th><th>Wlan-2天線</th><th>Wlan-3天線</th></tr><tr><td rowspan="3">Wlan卡 PCB板上接 口標示</td><td>"M"</td><td>"A"</td><td></td></tr><tr><td>"A"</td><td>"B"</td><td></td></tr><tr><td>"1"</td><td>"2"</td><td>"3"</td></tr></table> 注意：Wlan卡接口標示需按PCB板上的印刷字樣為主來區分！！														Wlan天線對應Wlan卡接口區分方式				天線	Wlan-1天線	Wlan-2天線	Wlan-3天線	Wlan卡 PCB板上接 口標示	"M"	"A"		"A"	"B"		"1"	"2"	"3"																										
Wlan天線對應Wlan卡接口區分方式																																																										
天線	Wlan-1天線	Wlan-2天線	Wlan-3天線																																																							
Wlan卡 PCB板上接 口標示	"M"	"A"																																																								
	"A"	"B"																																																								
	"1"	"2"	"3"																																																							
do	 <table><tr><th colspan="4">Antenna distinction method</th></tr><tr><th>Antenna Type</th><th>線材顏色</th><th>套筒顏色</th><th></th></tr><tr><td>Wlan-1</td><td>黑色</td><td>透明</td><td></td></tr><tr><td>Wlan-2</td><td>灰色</td><td>透明</td><td></td></tr><tr><td>Wlan-2</td><td>黑色</td><td>白色</td><td></td></tr><tr><td>Wlan-3</td><td>白色</td><td>透明</td><td></td></tr></table> The following table is for reference only, the actual product is based on the actual product. <table><tr><td>Wlan卡</td><td>3 1 2</td><td>Wlan卡</td><td>1 2</td><td>Wlan卡</td><td>1 2</td><td>Wlan卡</td><td>M A</td><td>Wlan卡</td><td>A B</td></tr><tr><td>Wlan卡</td><td>3 2 1</td><td>Wlan卡</td><td>2 1</td><td>Wlan卡</td><td>2 1</td><td>Wlan卡</td><td>A M</td><td>Wlan卡</td><td>B A</td></tr></table>														Antenna distinction method				Antenna Type	線材顏色	套筒顏色		Wlan-1	黑色	透明		Wlan-2	灰色	透明		Wlan-2	黑色	白色		Wlan-3	白色	透明		Wlan卡	3 1 2	Wlan卡	1 2	Wlan卡	1 2	Wlan卡	M A	Wlan卡	A B	Wlan卡	3 2 1	Wlan卡	2 1	Wlan卡	2 1	Wlan卡	A M	Wlan卡	B A
Antenna distinction method																																																										
Antenna Type	線材顏色	套筒顏色																																																								
Wlan-1	黑色	透明																																																								
Wlan-2	灰色	透明																																																								
Wlan-2	黑色	白色																																																								
Wlan-3	白色	透明																																																								
Wlan卡	3 1 2	Wlan卡	1 2	Wlan卡	1 2	Wlan卡	M A	Wlan卡	A B																																																	
Wlan卡	3 2 1	Wlan卡	2 1	Wlan卡	2 1	Wlan卡	A M	Wlan卡	B A																																																	
explain	The following steps 1, 2, 3, and 4 are for when the Wlan card is issued: 1 Take the WLAN card (A) NOTE: For Customer Consign Wlan . Apply "CONSIGN" sticker 2 Install the Wlan card on the interface, take the screw (B)* and lock it on the stud 3 Insert Wlan-1&wlan-2 antennas on the wlan card. Notes: 1. See the picture above for the wiring sequence of the Wlan card. 2. See picture 4 for the color distinction of the Wlan antennas. Arrange the Wlan antenna as shown in the picture, and attach Mylar (C) to the Wlan antenna and Wlan on the antenna head																																																									
bright	 <table><tr><th colspan="4">Antenna distinction method</th></tr><tr><th>Antenna Type</th><th>線材顏色</th><th>套筒顏色</th><th></th></tr><tr><td>Wlan-1</td><td>黑色</td><td>透明</td><td></td></tr><tr><td>Wlan-2</td><td>灰色</td><td>透明</td><td></td></tr><tr><td>Wlan-2</td><td>黑色</td><td>白色</td><td></td></tr><tr><td>Wlan-3</td><td>白色</td><td>透明</td><td></td></tr></table> The following table is for reference only, the actual product is based on the actual product. <table><tr><td>Wlan卡</td><td>3 1 2</td><td>Wlan卡</td><td>1 2</td><td>Wlan卡</td><td>1 2</td><td>Wlan卡</td><td>M A</td><td>Wlan卡</td><td>A B</td></tr><tr><td>Wlan卡</td><td>3 2 1</td><td>Wlan卡</td><td>2 1</td><td>Wlan卡</td><td>2 1</td><td>Wlan卡</td><td>A M</td><td>Wlan卡</td><td>B A</td></tr></table>														Antenna distinction method				Antenna Type	線材顏色	套筒顏色		Wlan-1	黑色	透明		Wlan-2	灰色	透明		Wlan-2	黑色	白色		Wlan-3	白色	透明		Wlan卡	3 1 2	Wlan卡	1 2	Wlan卡	1 2	Wlan卡	M A	Wlan卡	A B	Wlan卡	3 2 1	Wlan卡	2 1	Wlan卡	2 1	Wlan卡	A M	Wlan卡	B A
Antenna distinction method																																																										
Antenna Type	線材顏色	套筒顏色																																																								
Wlan-1	黑色	透明																																																								
Wlan-2	灰色	透明																																																								
Wlan-2	黑色	白色																																																								
Wlan-3	白色	透明																																																								
Wlan卡	3 1 2	Wlan卡	1 2	Wlan卡	1 2	Wlan卡	M A	Wlan卡	A B																																																	
Wlan卡	3 2 1	Wlan卡	2 1	Wlan卡	2 1	Wlan卡	A M	Wlan卡	B A																																																	
								The following steps 5 and 6 are for when the Wlan card is not available:																																																		
								5 Take the screw (B)* and lock it on the stud																																																		
								6. As shown in the figure, stick the Wlan antenna to the position shown on the motherboard and stick Mylar (C) on it.																																																		


model				Process code	file number	version	production date			Farewell (small)	Page (Small)	Site (Large)	Page (Large)	
NS5xx (except -E)		Install Wlan card		Establish	1		IE-2470	Reference 1	2021/7/14	12	3-2/16	25	2-2/31	
B O M	NO.	Description A1	Parts Number	Q'TY 1	Torque	Remark quality focus/notes:								
	WLAN card		6-88/998-N15CF-4210/-W			BY S/O 1. Wear an electrostatic bracelet during work 1. Electrostatic bracelet								
	A2 WLAN card		6-88-NV40F-4210			BY S/O 2. Fixture hanging height (i.e.: pallet y height of the lowest point of the fixture) y38 cm 2. Electric driver, self-supplied screw machine								
	A3 WLAN card		6-88/988-N24GF-4200/-HL			BY S/O 3. Lock the screws in order, and be careful not to slip or miss the lock.								
	A4 WLAN card		6-988-NV40F/L140F-4210-HL			BY S/O								
	A5 WLAN card		6-88-X270F-4210	1 1 1 1		BY S/O								
	A6 WLAN card		6-88-NL5RF-7000	1		BY S/O								
	B screw C Mylar		6-35-Z9120-3R2	1	1.5±0.2	Standard configuration								
			6-40-M55J2-030	1										

For NS50PU/AU

Hold

do

explain



Wlan天線對應Wlan卡接口區分方式			
天線	Wlan-1天線	Wlan-2天線	Wlan-3天線
Wlan卡 PCB板上接 口標示	"M"	"A"	
	"A"	"B"	
	"1"	"2"	"3"

注意：Wlan卡接口標示需按PCB板上的印刷字樣為主來區分！！！！

Antenna distinction method			
Antenna Type	線材顏色	套筒顏色	
Wlan-1	黑色	透明	
Wlan-2	灰色	透明	
Wlan-2	黑色	白色	
Wlan-3	白色	透明	

The following table is for reference only, the actual product is based on the actual product.

Wlan卡	Wlan卡	Wlan卡	Wlan卡	Wlan卡	Wlan卡
3 1 2	3 1 2	3 1 2	3 1 2	3 1 2	3 1 2
1 2 3	1 2 3	1 2 3	1 2 3	1 2 3	1 2 3
2 1 3	2 1 3	2 1 3	2 1 3	2 1 3	2 1 3

The following steps 1, 2, 3, and 4 are for when the Wlan card is issued:

1 Take the WLAN card (A)

NOTE: For Customer Consign Wlan . Apply "CONSIGN" sticker


2 Install the Wlan card on the interface, take the screw (B)* and lock it on the stud

3 Insert Wlan-1&wlan-2 antennas on the wlan card. Notes: 1.

See the picture above for the wiring sequence of the Wlan card.

2. See picture 4 for the color distinction of the Wlan

antennas. Arrange the Wlan antenna as shown in the picture, and attach Mylar (C) to the Wlan antenna and Wlan on the antenna head



The following steps 5 and 6 are for when the Wlan card is not available:

5 Take the screw (B)* and lock it on the stud

6. As shown in the figure, stick the Wlan antenna to the position shown on the motherboard and stick Mylar (C) on it.


model		Process code		file number	version	production date	Site (small) Page (small)		Site (large) Page (large)		
NS5xx (except -E)		Install SPK		Establish	1	IE-2470 Part 1	2021/7/14	12	3-3/16	26	2-1/31
B O M	NO.	Description A SPK-	Parts Number	Q'TY 1	Torque	Remark quality	oints/notes: 1. Wear an electrostatic bracelet during work		Tools/Supplies: 1. Static electricity bracelet		
	L B SPK-R		6-23-5NS5P-0L0/5NS50-0L1								
			6-23-5N130-0R2-1/5NS5P-0R0	1							

Hold

do

explain

bright



- 1 Take SPK-L (A) & SPK-R (B) and align them with the positioning posts and install them at the positions shown in the upper cover.
- 2 As shown in the figure, arrange the SPK-L cable through the hook 1, and arrange the excess cable in the position shown in the picture.
- 3 Plug the SPK-L & R cables into the motherboard interface
4. Remove the adhesive tape 1, 2 and 3 shown in the picture.

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name



The limited period of the SOP on this page is: 2023/7/27~~2023/10/27

model				Process code	file number	version	production date			Site (small)	Page (small)	Site (large)	Page (large)		
NS5xx (except -E)		Flash the motherboard		Establish	1		IE-2470 Part 1		2021/7/14	13		2-1/16	26	2-2/31	
B O M	NO.	Description	Parts Number	Q'TY 1	Torque		Remark quality	points/notes: 1. Wear an electrostatic bracelet during work				Tools/Supplies: 1. Static electricity bracelet 2. Brushing the gun 3. Computer			
	A RAM		BY SO												

Hold

do

explain



1. Flash the machine & motherboard barcode into the system
2. Paste the barcode on the motherboard. The font direction of the barcode is consistent with the direction of the mainboard material number of the laser engraving strip on the motherboard.
3. Install RAM (A)----(Install the right card slot RAM1 first, then install the left card slot RAM2)
- When 4 pins come out of the RAM: stick a monthly mark on the RAM -----The direction of the monthly mark is consistent with the font direction of the incoming material label
5. For customers to Consign RAM, put a "Consign sticker" on the RAM to replace the monthly label.



KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/27~~2023/10/27

model				Process code	file number	version	production date			Farewell (small)	Page (Small)	Site (Large)	Page (Large)	
NS5xx (except -E)		Install M.2 SSD		Establish	1		IE-2470	Reference 1	2021/7/14	13	2-2/16	27	2-1/31	
B O M	NO.	Description	Parts Number	Q'TY 1	Torque	Remark	Quality Focus/Notes: Tools/Supplies:							
	The SSD		By S/O	or 2	1		W/ SSD	1. Wear an electrostatic bracelet during work 1. Electrostatic bracelet						
	B SSD screw		6-35-Z9120-3R2	or 2	1			2. The hanging height of the fixture (ie: pallet y height of the lowest point of the fixture) y 38 cm 2. Electric driver, self-supplied screw machine						
	C Thermal Pad		6-48-L1402-010	or 2				3. Lock the screws in order, and be careful not to slip or miss the lock.						

Hold

do



explain

When using 1 SSD (except SATA SSD):

- 1 Attach THERMAL PAD (C2) to the position shown in the picture in slot 2 of the motherboard
2. Take the SSD card (A2) and put the monthly label on the SSD

card. Note: For the customer's Consign SSD card, put the "Consign sticker" instead of the monthly label.

- 3Insert the SSD card into the card slot 2 interface and secure it with the screw (B2)

When a SATA SSD is produced: 4. Paste

- THERMAL PAD (C1) on the motherboard card slot 1 as shown in the figure 5. Take the SSD card (A1) and paste the monthly mark on the SSD card. Note:

For customers to Consign SSD cards, paste the "Consign sticker" , replace the monthly mark 6 ,

- insert the SSD card into the card slot 1 interface, and take out the screw (B1) to

lock it. Note : SATA SSD can get the word SATA in the BOM or first article description according to the material number.

When targeting 2 SSDs:

- 7 Paste THERMAL PAD (C)*2 in the white frame of the motherboard
8. Take 2 SSD cards (A) and paste the monthly label on the SSD card.

Note: For customers to Consign SSD cards, paste the "Consign sticker" to replace the monthly label.

- 9 Insert the SSD card into the interface and take out the screw (B)*2 to

secure it. Note: For W/SSD*2, the SSD with OS installed in the GEN4*4 slot/If the highest specification of the model is GEN3*4, then Installed in GEN3*4 card slot.

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/27~~2023/10/27



model			Process code		file number	version	production date		Site (small) Page (small)		Site (large) Page (large)		
NS5xx (except -E)		Install battery		Establish	1		IE-2470 Part 1		2021/7/14	14	4-1/16	27	2-2/31
B O M	NO.	Description	Parts Number	Q'TY 1 3	Torque		Remark quality	focus/notes: 1. Wear an electrostatic bracelet BY MO during			Tools/Supplies: 1. Static electricity bracelet		
	A Battery	B Lala	6-87-L140S-32B02/32B03										
	glue		6-47-0019L-010				work						
	This page is for 36W battery operations												

Hold

do

explain

bright



- As shown in the picture, apply the pull-up adhesive (B)*3 to the upper cover and remove the backing adhesive (for new upper covers: 6-39-NS502-013/-xx & 6-39-NS512-011/-xx do not need to be applied Attached)
- Plug the battery cable into the motherboard interface
- Install the battery (A) on the top cover as shown in the picture



model			Process code		file number	version	production date			Site (small)	Page (small)	Site (large)	Page (large)	
NS5xx (except -E)		Install battery		Establish	1		IE-2470 Part 1		2021/7/14	14		4-2/16	28	2-1/31
B O M	NO.	Description	Parts Number	Q'TY 1 3	Torque		Remark quality	focus/notes: 1. Wear an electrostatic bracelet BY MO during operation			Tools/Supplies: 1. Static electricity bracelet			
	A Battery	B Lala	6-87-L140S-72B01/72B02											
	glue		6-47-0019L-010				operation							
	This page is for 73W battery operations													

Hold

do

explain

bright



- As shown in the picture, apply the pull-up adhesive (B)*3 to the upper cover and remove the backing adhesive (for new upper covers: 6-39-NS502-013/-xx & 6-39-ns512-011/-xx do not need to be applied Attached)
- Plug the battery cable into the motherboard interface
- Install the battery (A) on the top cover as shown in the picture

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/27~~2023/10/27

model				Process code	file number	version	production date			Site (small) Page (small)	Site (large) Page (large)		
NSSxx (except -E)		Install battery		Establish	1		IE-2470 Part 1		2021/7/14	14	4-3/16	28	2-2/31
B O M	NO.	Description	Parts Number	Q'TY	Torque	Remark quality	focus/notes: 1. Wear an electrostatic bracelet during operation 2. Pressing time: 10s 3. Pressure: 0.3-0.4 Mpa				Tools/Supplies: 1. Static electricity bracelet 2.NS50 battery assembly jig: NS50MU-YH04-1002-01		

Hold

do

explain



- 1 Take the machine and place it in the jig as shown in the figure, start the jig to press the battery, the pressing time is: 10s
- 2 After pressing is completed, take out the machine

bright


model				Process code	file number	version	production date		Site (small) Page (small)	Site (large) Page (large)		
NSSxx (except -E)		Fixture lower case		Establish	1		IE-2470 Part 1	2021/7/14	14	4-4/16	29	2-1/31
	NO.	Description A	Parts Number	Q'TY 1	Torque	Remark quality	focus/notes: Tools/consumables:					
	Jig lower cover B Jig		6-39-xxxxxx				1. Wear an electrostatic bracelet during work 1. Electrostatic bracelet					
	lower cover screws		6-35-1-B1120-4RC-1	0.3	2.0±0.2		2. The hanging height of the fixture (i.e.: pallet y height of the lowest point of the fixture) y 38 cm 2					
							3. Lock the screws in order, and be careful not to slip or miss the lock.					

Hold

do

explain

bright



1 Take the lower cover (A) of the fixture and install it on the machine

2. Take a total of 3 fixture screws (B1~B3) to lock the lower cover.

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name


The limited period of the SOP on this page is: 2023/7/27~~2023/10/27

model				Process type	Code file number	version production	date		Farewell (small)	Page (Small)	Site (Large)	Page (Large)	
NS5xx (except -E)		K/B processing		Establish	1	IE-2470	Reference 1	2021/7/14	15	3-2/16	30	2-1/31	
B O M	NO.	Description	Parts Number	Q'TY	Torque	Remark quality points	nts/notes: for non-illuminated keyboards				Tools/Supplies:		
	A Mylar		6-40-NS502-041	1			1. Wear an electrostatic bracelet during work				1. Static electricity bracelet		

Hold

do

explain



The following steps are for working with a non-illuminated keyboard

1 As shown in the picture, paste K/B Mylar(D) in the K/B frame of the upper cover

Be careful not to climb walls when attaching K/B Mylar

bright

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/27~~2023/10/27


model				Process code	file number	version	production date			Site (small) Page (small)	Site (large) Page (large)		
NS5xx (except -E)		Install K/B		Establish		1	IE-2470 Part 1		2021/7/14	15	3-3/16	30	2-2/31
B O M	NO.	Description	Parts Number	Q'TY	Torque	Remark	quality points/notes: 1. Wear an electrostatic bracelet during work	Tools/Supplies: 1. Static electricity bracelet					

Hold

do

explain

bright



The following steps 1, 2, and 3 work when K/B appears

1 Take K/B and paste the barcode on K/B

Note that the direction of the barcode is consistent with the font direction of the incoming material label. The barcode cannot cover the incoming material label.

2 Plug the keyboard cable into the motherboard

Pay attention to plug in the large cable first, then the small cable——when targeting the illuminated keyboard

3. Snap the keyboard onto the upper cover and make sure the hook is fully engaged.

Note 1. First snap the bottom edge of the keyboard into the upper cover, then snap it into both sides and the top

2. Before engaging the keyboard, check that the K/B cable is not wrinkled

model				Process code	file number	version	production date			Site (small) Page (small)	Site (large) Page (large)		
NSSxx (except -E)		General inspection		Establish	1		IE-2470 Part 1	2021/7/14		16	2-1/16	31	2-1/31
B O M	NO.	Description	Parts Number	Q'TY	Torque	Remark	quality	points/notes: 1. Wear an electrostatic bracelet during work				Tools/Supplies: 1. Static electricity bracelet	

Hold

do

explain

bright



- 1. Check that the screws on the lower cover of the fixture are not leaked or scratched.
- 2 Check that the battery must be locked
- 3 Check that there is no gap in the lower part of the machine
- 4. Check that there are no gaps or scratches on the hinge side of the machine.
- 5 Check the USB interface: the inside of the USB 2.0 interface is black, and the inside of the USB 3.0 interface is blue.

model				Process code file number version		production date		Site (small) Page (small)		Site (large) Page (large)									
NS5xx (except -E)		General inspection		Establish		1		IE-2470 Part 1		2021/7/14		16		2-2/16		31		2-2/31	
B O M	NO.	Description	Parts Number	Q'TY	Torque	Remark quality	points/notes: 1. Wear an electrostatic bracelet during operation 2. Increase the illumination value: 800~1200lm/y						Tools/Supplies: 1. Static electricity bracelet 2. Thick and thin rules						
Hold <																			

Note: 1. To activate the power, plug in the AC and wait for 6 seconds, press the power button on the AC to turn on the phone, and pull out the AC after turning on the phone. 2: The gap between the LCD and the front cover should not exceed 0.8mm below, and no single point protrudes on both sides; 3 : For defective machines, record the defective phenomena in the process card

Test the AUTO LOCK function (see Figure 9 for details)
Note: With the opening upward, stand the machine 90 degrees and check with the thickness gauge. GAPy5mm is OK.
1. For new models after 1500PCS, first piece measurement
2. For new models within 1500 PCS, first make a visual inspection. If the visual inspection GAP is too large, use a thickness gauge to measure it.

Review check: Qian Lin

Written by:Song Zhiheng

1