





KAPOK Standard Operation PROCEDURE Operation Instructions Operation Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model		Process Type Station Type			Version	code	File No	production date	Site (small) Page (small) Site (large) Page (large)					
NS7xx		Check the back cover			Establish	1	Reference 1	1	IE-2525	2021.03.24	1	3-1/16	1	1-1/31
B O M	NO.	Description	Parts Number	Q'TY	Torque	Remark	Quality Key Points/Notes: 1. Wear an electrostatic bracelet during operation BY			Tools/Supplies: 1. Static electricity bracelet 2. Soft protective film 3. Protective film cutting jig				
	A For details on the back cover, see 1-5			1										
	B acetate cloth 6-40-00150-760			4		M/O								
								This site has 6 pages in total, this is page 1						
Hold														
do														
explain														
bright														
	1. Take the back cover (Ax) and check the appearance according to the standard. Cut a soft protective film of appropriate size and stick it on the back cover.													
	Note: 1. Check that the logo on the back cover must be pressed correctly, no words may be dropped, no words may be offset, and the neutral logo must be pasted correctly.													
2. Press the logo back and forth 3 to 5 times, and peel off the protective film on the logo in parallel.														
3. Paste a small protective film on the logo, and finally apply a soft protective film														
The following steps are for when the new front frame is matched with the old back cover (i.e. the back cover 6-39-NS711-020 is matched with the front frame 6-39-NS701-013)														
2. Attach 4pcs conductive cloth (B) to the hinge of the back cover as shown in the picture.														

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model				Process	specific version		Code production date	File No		Site (small)	Page (small)	Site (large)	Page (large)
NS7xx		Install Hinge on the back cover		Establish	2	Reference 1	1	IE-2525	2021.03.24	1	3-2/16	2	1-1/31
B O M	NO.	Description	Parts Number	Q'TY 1 1	Torque	Remark quality	ocus/notes: Tools/consumables:			This site has 2 pages in total, this is page 2			
	A Hinge-R		6-33-NS701-0R0	6			1. Wear an electrostatic bracelet during work 1. Electrostatic bracelet						
	B	Hinge-L	6-33-NS701-0L0				2. The hanging height of the jig (that is: the height of the pallet y the lowest point of the jig) y 38 cm 2. Electric screwdriver						
	C screw		6-35-B6125-2R5		1.5±0.2		3. Lock the screws in order, and be careful not to slip or miss the lock.						
Hold	  												
do													
explain													
bright	1 Take Hinge-R (A) & Hinge-L (B) and align the positioning posts and install them on the back cover												
	2. Take the screws (B)*6 to lock the Hinge on the back cover (the one with the triangle symbol on the body)												
	Note: 1. The CCD cable does not allow for rotation of the shaft												
2. The LCD cable does not allow the hinge to rotate													

KAPOK Standard Operation PROCEDURE Operation Instructions

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model		Job name		Process station type		Version	code		File No	production date		Page
NS7xx		Back cover material number details		Establish	1	Reference 1	1		IE-2525	2021.03.24		3-3/16
B O M	NO.	Description	Parts Number	Q'TY	Torque	Remark	NO.	Description	Parts Number	Q'TY	Torque	Remark
		A1 back cover (BY SO) 6-39-NS701-022/-023		1								
		A2 back cover (BY SO) 6-39-NS701-022/-023-xx		1								
		A3 back cover (BY SO) 6-39-NS711-020/-021		1								
		A4 back cover (BY SO) 6-39-NS711-020-xx		1								
		A5 back cover (BY SO)		1								
		A6 back cover (BY SO)		1								
		A7 back cover (BY SO)		1								
		A8 back cover (BY SO)		1								
		A9 back cover (BY SO)		1								
		A10 back cover (BY SO)		1								
		A11 back cover (BY SO)		1								
		A12 back cover (BY SO)		1								
		A13 back cover (BY SO)		1								
		A14 back cover (BY SO)		1								
		A15 back cover (BY SO)		1								
		A16 back cover (BY SO)		1								
		A17 back cover (BY SO)										
		A18 back cover (BY SO)										
		A19 back cover (BY SO)										
		A20 back cover (BY SO)										
		A21 back cover (BY SO)										
		A22 back cover (BY SO)										
		A23 back cover (BY SO)										
		A24 back cover (BY SO)										
		A25 back cover (BY SO)										
		A26 back cover (BY SO)										

KAPOK Standard Operation PROCEDURE Operation Instructions Operation Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model		Process Type Station Type				Version	Code file number production date			Site (small) Page (small) Site (large) Page (large)			
NS7xx		Processed back cover		Establish	1	Reference 1	1	IE-2525	2021.03.24	2	3-1/16	3	2-1/31
B O M	NO.	Description A Lala	Parts Number	Q'TY 2.2	Torque	Remark	Quality focus/precautions: 1. Wear an electrostatic bracelet during operation			Tools/Supplies: 1. Static electricity bracelet			
	gum		6-47-0019L-014/01B										
							This site has 6 pages in total, this is page 2						
Hold													
do													
explain													
bright	1. Attach the zipper (A)*2 to the back cover according to the marked line in the figure, and remove the zipper backing. Note: The rubber ears should be facing the Hinge.												

1

KAPOK Standard Operation PROCEDURE Operation Instructions Operation Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model	Process Type Station Type			Version	Code file number production date		Site (small) Page (small) Site (large) Page (large)		
NS7xx	Processed back cover			Establish	1	IE-2525	2021.03.24	2	3-2/16
B O M	NO.	Description A Lala	Parts Number	Q'TY 2.2	Torque	Remark	Quality focus/precautions: 1. Wear an electrostatic bracelet during operation Tools/Supplies: 1. Static electricity bracelet		
	gum		6-47-0019L-014/01B						
This site has 6 pages in total, this is page 2									

Hold

This page is only for 6-50-NBB35-V011/V020 LCD operations:

Lala rubber ears

A1

A2

Lala rubber ears

1. Stick the pull-up adhesive (A)*2 on the back of the LCD according to the marked line in the figure, and remove the pull-up adhesive backing.

Note: The rubber ears should be facing the Hinge.

do

explain

bright

KAPOK Standard Operation PROCEDURE Operation Instructions Operation Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model		Station Type			Process type		Version		Code file number		production date		Site (small) Page (small)		Site (large) Page (large)									
NS7xx		Install CCD			Establish		2		Reference 1		1		IE-2525		2021.03.24		2		3-3/16		4		1-1/31	
B O M	NO.	Description	Parts Number	Q'TY 1	Torque	Remark	Quality focus/precautions: By S/O							Tools/Supplies: 1. Static electricity bracelet 2. Cable management stick <										

KAPOK Standard Operation PROCEDURE

Operation Instructions


Operation Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model	Process Type Station Type			Version	Code production date	File No		Site (small) Page (small)	Site (large) Page (large)	
NS7xx	Check LCD	Establish	3	Reference 1	1	IE-2525	2021.03.24	3	2-1/16	5 2-1/31

B O M	NO.	Description	Parts Number	Q'TY 1 1	Torque	Remark quality focus	notes: 1. Wear an electrostatic bracelet during operation By S/O By S/O	Tools/Supplies: 1. Static electricity bracelet 2. Brushing the gun 3. Computer
	A LCD		BY S/O	1				
	B1 LCD cable		6-43-NS701-011-C/1C					
	B2 LCD cable		6-43-NS701-020-C/1C					
	C MYLAR		6-40-M55J2-030	1				


This site has 2 pages in total, this is page 1



Brush the barcode here on the back cover of Mofa



barcode



Apply warranty sticker



LCD body barcode

1. Take the LCD (A) and check the appearance according to the standard. **Note: A. Tear off the LCD protective film and check whether the LCD is cracked.**


2. Take the process card and swipe the barcode, and place the process card on the pallet. 3. Swipe the LCD barcode and click on the LCD to enter the system.

4. For the Mofa back cover, swipe the back cover barcode (Cxxxxxxx) into the system

Note: When the Mofa back cover flows down with the thread, it cannot be taken out from the non-woven bag.

5. Attach the LCD warranty sticker to the back of the LCD----located in the lower left corner

1




Peel off the adhesive tape and stick it on the LCD

Plug the LCD cable into the LCD interface

Bx

Mylar (C) cannot exceed the edge of the LCD PCBA board



透明mylar貼附同對策三,由正面包裹到背面(注意
貼附再LCD cable出線端的一頭)

6 Take the LCD cable (B) and insert it into the LCD interface (the LCD cable must be inserted all the way)

7. Tear off the adhesive tape on the cable tie and stick it on the LCD.

8 Attach 1pcs mylar from the front to the back at the position shown in the picture above (note: attach to the other end of the LCD Cable outlet)

2

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

[illegible]

KAPOK Standard Operation PROCEDURE Operation Instructions Operation Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model	Process Type Station Type			Version	code	File No	production date	Site (small) Page (small)	Site (large) Page (large)		
NS7xx	Processed back cover	Establish	1	Reference 1	1	IE-2525	2021.03.24	4	4-1/16	6	2-1/31

B O M	NO.	Description	Parts Number	Q'TY	Torque	Remark	Quality focus/precautions: Tianside 1. Wear an electrostatic bracelet on the left side during operation	Tools/Supplies: 1. Static electricity bracelet
	A Rubber		6-47-NS501-031	2.2				
	B Rubber		6-47-NS701-010	2.2				
This site has 6 pages in total, this is page 3								


Hold

do


explain

bright

A1




B1



For manual attachment of LCD



A2



1 As shown in the picture, attach Rubber (A)*2 & (B)*2 to the position shown on the back cover.

KAPOK Standard Operation PROCEDURE Operation Instructions Operation Name												The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26			
model		Process Type Station Type					Version	Code production date	File No		Site (small) Page (small) Site (large) Page (large)				
NS7xx		Processed back cover			Establish	1	Reference 1	1	IE-2525	2021.03.24	4	4-2/16	6	2-2/31	
B O M	NO.	Description	Parts Number	Q'TY 4.4	Torque	Remark	Quality focus/precautions: 1. Wear an electrostatic bracelet during operation				Tools/Supplies: 1. Static electricity bracelet				
	A Rubber		6-47-NS701-010												
							This site has 6 pages in total, this is page 4								
Hold	For LCD:6-50-NBB35-V020/-V011 operation 														
do															
explain															
bright	1 Attach Rubber (A)*4 to the position shown on the back cover as shown in the picture														

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model		Process	specific version		Code production date	File No		Site (small)	Page (small)	Site (large)	Page (large)
NS7xx	Install LCD on the back cover	Establish	3	Reference 1	1	IE-2525	2021.03.24	4	4-3/16	7	2-1/31

B O M	NO.	Description	Parts Number	Q'TY	Torque Remark	quality points/notes: 1. Wear an electrostatic bracelet during operation	Tools/Supplies: 1. Static electricity bracelet 2. Cable management stick
							This site has 2 pages in total, this is page 2


Hold



Mount the LCD on the back cover in the upper left corner

The monthly mark cannot exceed the alignment line and must be placed squarely

do




For LCD:6-50-NBB35-V020/-V011 operation

Install the LCD on the back cover at the lower left corner

The monthly mark cannot exceed the alignment line and must be placed squarely

explain



Trunk 3

Trunk 2

Trunk 1

Hook 3

Hook 2

Hook 1

bright

1 Install the LCD on the back cover along the upper left corner of the back cover as shown in the figure

2 Press the adhesive position on the back cover to make the LCD and back cover stick better

3. Paste the moon mark on the LCD as shown in the picture

Note: a. The monthly mark should not exceed the bottom edge of the LCD and should be posted squarely (numbers font upward)

b. For customer Consign LCD, put "CONSIGN" sticker instead of monthly label

c. For trial production models, this monthly label does not need to be attached.

3. As shown in the figure, the LCD cable hook 1-cable 1-hook 2-cable 2-cable 3-cable 3

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model		Process type	stand farewell	Version	Code production date	File No		Site (small) Page (small)	Site (large) Page (large)		
NS7xx	Install HINGE CAP on the back cover	Establish	4	Reference 1	1	IE-2525	2021.03.24	4	4-4/16	8	1-1/31
B O M	NO.	Description	Parts Number	Q'TY 1	Torque	Remark quality focus	notes: Tools/consumables: 1. Wear an electrostatic bracelet during work 1. Electrostatic bracelet 2. The hanging height of the jig (that is: the height of the pallet y the lowest point of the jig) y 38 cm 2. Electric screwdriver 3. Lock the screws in order, and be careful not to slip or miss the lock.				
	A HINGE	COVER	6-42-NS701-102								
	B HINGE	CAP-L	6-42-NS701-052/-053								
	C HINGE	CAP-R	6-42-NS701-062/-063								
	D screw		6-35-B6120-3RD	1 1 4	1.5±0.2		This site has 2 pages in total, this is page 2				

Hold

do

explain

bright

1 Take HINGE COVER (A) and check the appearance according to the standard

Note: If the incoming material comes with its own adhesive, remove the adhesive.

2 Install HINGE COVER on the back cover

3. Take HINGE CAP (B) (C), check the appearance according to the standard, and install it on the back cover.

4 Pull all the wires at the left hinge back and forth 2 to 3 times, and check that the front and rear covers are combined with the left hinge so that no wires are caught.

5 Take out the screws (D)*4 and lock the HINGE GAP as shown in the figure

Review check:Qian Lin

Write write:Song Xingxing

model	Process Type Station Type			Version	code	File No	production date	Site (small) Page (small)	Site (large) Page (large)		
NS7xx	Post Mylar	Establish	5	Reference 1	1	IE-2525	2021.03.24	5	3-2/16	10	1-1/31


B O M	NO.	Description A	Parts Number	Q'TY 2.1	Torque	Remark	Quality focus/precautions: 1.	Tools/Supplies: 1. Static electricity bracelet 2. Plastic tweezers
	Mylar		6-40-NS501-050/-051				Wear an electrostatic bracelet during operation	
							This site has 2 pages in total, this is page 2	

Hold

do

explain

bright



1. Take Mylar (A)*2 and stick it on the front frame as shown in the picture with plastic tweezers.



1

KAPOK Standard Operation PROCEDURE Operation Instructions Operation Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model		Process Type Station Type				Version	code	File No	production date	Site (small) Page	(small) Site (large)	Page (large)		
NS7xx		Processing T/P			Establish	6	Reference 1	1	IE-2525	2021.03.24	5	3-3/16	11	1-1/31
B O M	NO.	Description	Parts Number	Q'TY 1	Torque	Remark	Quality focus/precautions: 1. Wear an electrostatic bracelet during operation 2. Fixture pressing time: 10s 3. Fixture pressure: 5.9~6.9kgf/cm²/0.59~0.69MPa			Tools/Supplies: 1. Static electricity bracelet 2.Click PAD fitting limiter 3.NS70/NP70 TP iron assembly jig 4. Thick and thin rules				
	A1 Click PAD		By M/O											
	A2 Click PAD		6-49-NL7P3-011	1										
	B	Click PAD BKT	6-33-NS702-080	1										
								This site has 2 pages in total, this is page 1						

Hold





Click pad fits the dots at the bottom of the jig
Dot attachment on Click pad

Align to upper left corner

Ax

do



Take the processed Click PAD and use 0.1
The thickness gauge confirms that the iron parts in this area are consistent with
Whether the PAD fits in place

explain

1

Take Click PAD BKT (B), tear off the release paper and place it in the Click PAD laminating jig.
Remarks: Fitting fixture number: Click PAD fitting limit fixture

2

Take Click PAD (A) and align the upper left corner as shown in the picture to fit it.
3 Place the processed Click PAD in the iron pressing fixture for pressing. The pressing time is 10S.
Remarks: Pressing fixture number: NS70/NP70 TP iron parts pressing fixture

4



Take the processed Click PAD and use a 0.1 thickness gauge to confirm whether it fits in place.

bright

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

This site has 2 pages in total, this is page 2

bright



KAPOK Standard Operation PROCEDURE Operation Instructions Operation Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26


model		Process Type Station Type				Version	Code production date	File No		Site (small) Page	(small) Site (large)	Page (large)		
NS7xx		Install TP MYLAR			Establish	6	Reference 1	1	IE-2525	2021.03.24	6	2-2/16	12	2-2/31
B O M	NO.	Description	Parts Number	Q'TY 1	Torque	Remark	Quality focus/precautions: 1. Wear an electrostatic bracelet during operation 2. Pressing time: 5s 3. Pressure value: 5.9~6.9kgf/cm³			Tools/Supplies: 1. Static electricity bracelet 2. Robotic arm				
	A1 TP MYLAR		6-40-NS702-030			Standard								
	A2 TP MYLAR		6-40-NS712-010	1		100%Inspection Standard configuration								
								This site has 2 pages in total, this is page 2						

Hold

do

explain

bright



1 Place the upper cover into the fixture as shown in the figure

Note that the upper cover is placed with the front facing up and must be placed in place.

2 Press the start button and the robot arm attaches to the T/P mylar. Laminating T/P mylar, laminating time 5s

3. Take out the upper cover that has been processed and inspect the appearance.

NOTE: Check if TP mylar is centered

Press the TP part to confirm whether the TP mylar interferes with the upper cover.

4. Take out the upper cover, cut a soft protective film of appropriate size and stick it on the TP of the upper cover.

1

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model		Process	specific version		Code production date	File No		Site (small)	Page (small)	Site (large)	Page (large)
NS7xx	Install K/B small card	Establish	7	Reference 1	1	IE-2525	2021.03.24	7	2-1/16	13	1-1/31

B O M	NO.	Description	Parts Number	Q'TY 1 2	Torque	Remark quality	ocus/notes:	Tools/Supplies:
	AK/B small card		6-77-NS707-D01			BY SO 1.	1. Wear an electrostatic bracelet during work 1. Electrostatic bracelet	
	B screw		6-35-B6120-2RE		1.5±0.2		2. The hanging height of the jig (that is: the height of the pallet y the lowest point of the jig) y 38 cm 2.	Electric screwdriver
	C	K/B cable arrangement	6-43-NS700-051/-1	1			3. Lock the screws in order, and be careful not to slip or miss the lock.	
	DK/B cable		6-43-NS700-041/-1	1				
This site has 2 pages in total, this is page 1								

Hold

do

explain

bright

1 Take the K/B small card (A) and install it on the upper cover as shown in the figure, and secure it with 2 screws (B)

2 Take the K/B cables (C) & (D) and insert them into the K/B small card interface. Tear off the cable mylar release paper to fix the cables on the small card.

3. Tear off the adhesive at the bottom of the K/B cable (C) & (D) and stick it to the upper cover.

1

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model		Process	specific version		Code production date	File No		Site (small)	Page (small)	Site (large)	Page (large)
NS7xx	Install Wlan antenna	Establish	7	Reference 1	1	IE-2525	2021.03.24	7	2-2/16	14	1-1/31

B O M	NO.	Description	Parts Number	Q'TY 1 1	Torque	Remark quality p	prints/notes: 1. Wear an electrostatic	Tools/Supplies: 1. Static electricity bracelet
	A Wlan-1 antenna		6-23-7NS70-010				bracelet during work	
	B Wlan-2 antenna		6-23-7NS70-020					
							This site has 2 pages in total, this is page 2	

Hold

do

explain

bright

1. Tear off the adhesive on the Wlan-1 antenna (A) body and install it on the upper cover as shown.

2. Peel off the adhesive backing of copper foil 1 and stick copper foil 1 vertically on the upper cover

3. Tear off the Mylar release paper that comes with the incoming material and fix the Wlan-1 antenna as shown in the figure.

4. Tear off the adhesive on the Wlan-2 antenna (B) body and install it on the upper cover as shown.

5. Tear off the adhesive on the copper foil 2 and stick the copper foil 2 vertically on the upper cover.

6. Tear off the Mylar release paper that comes with the incoming material and stick it on the copper foil 2

Note that copper foil 2 needs to be attached under the mylar on the upper cover. The Wlan antenna copper foil needs to be attached vertically and pressed flatly.

7 As shown in the figure, the WLAN-2 antenna passes through hook 1-hook 2-hook 3

model		Process	specific version		Code production date	File No		Site (small)	Page (small)	Site (large)	Page (large)
NS7xx	Combined with Hinge on the right	Establish	8	Reference 1	1	IE-2525	2021.03.24	8	2-1/16	15	1-1/31


B O M	NO.	Description A	Parts Number	Q'TY 3	Torque	Remark quality	ocus/notes: Tools/consumables:	
	screw		6-35-82125-6RA		2.5±0.2		1. Wear an electrostatic bracelet during work 1. Electrostatic bracelet	
							2. The hanging height of the jig (that is: the height of the pallet y the lowest point of the jig) y 38 cm 2. Electric screwdriver	
							3. Lock the screws in order, and be careful not to slip or miss the lock.	
							This site has 2 pages in total, this is page 1	

Hold

do

explain

bright



1 Take the upper cover and vertically combine the upper cover with the LCD upper body

2 Combine the right Hinge and take screws (A)*3 to lock the right Hinge (the one with a triangle symbol on the body)

Note: The upper cover screw holes and Hinge screw holes must be aligned

1


KAPOK Standard Operation PROCEDURE Operation Instructions Operation Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model	Process Type Station Type			Version	code	File No	production date	Site (small) Page (small)	Site (large) Page (large)		
NS7xx	Install HALL SENSOR small card	Establish	8	Reference 1	1	IE-2525	2021.03.24	8	2-2/16	16	1-1/31

B O M	NO.	Description	Parts Number	Q'TY 1	Torque	Remark quality focus	notes: Tools/consumables:				
	A	HALL SENSOR small card/					1. You need to wear an electrostatic bracelet during operation 2. The hanging height of the fixture (i.e.: the height of the pallet y the lowest point of the fixture) y38 cm 3. Lock the screws in order, and be careful not to slip or miss the lock.				
	B	LID TO MB cable	6-43-NS700-011/-1	1							
	C	screw	6-35-B1120-4RC/-1	1	1.5±0.2						

This site has 2 pages in total, this is page 2




1. Take the HALL SENSOR small card (A), open the HALL SENSOR small card interface baffle, take the cable (B) with the word LID on one end and insert it into the corresponding interface of the small card, and snap the baffle to fix the cable.
2. Tear off the cable mylar release paper to fix the cable on the small card.
3. Take the processed HALL SENSOR small card and install it on the upper cover as shown in the picture, and take out the screw (C)*1 to lock it.
4. Peel off the adhesive at the bottom of the cable and stick it on the upper cover.
- 5 As shown in the figure, the CCD cable passes through hook 1-hook 2-hook 3-hook 4-hook 5


KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model				Process	specific version		Code production date	File No		Site (small)	Page (small)	Site (large)	Page (large)
NS7xx		Locking the motherboard		Establish	9	Reference 1	1	IE-2525	2021.03.24	9	2-1/16	17	1-1/31
B O M	NO.	Description	Parts Number	Q'TY 1 1	Torque	Remark quality focus/notes: Tools/consumables:							
	A	motherboard B	6-77-NS5xxx-xxx-xx /			1. Wear an electrostatic bracelet during work 1. Electrostatic bracelet							
		MULTI small card				2. The hanging height of the jig (that is: the height of the pallet y the lowest point of the jig) y 38 cm 2. Electric screwdriver							
	C screw D	screw E	6-35-B6120-2RE	3	1.5±0.2	3. Lock the screws in order, and be careful not to slip or miss the lock.							
		MYLAR	6-35-B1120-4RC/-1		1.5±0.2								
			6-40-P7751-030	1 1									
This site has 2 pages in total, this is page 1													
Hold													
do													
explain													
bright													



Install the motherboard from here



1 Take out the motherboard (Ax) and check the motherboard material number and version

2 Attach 1pcs mylar (E) at the position shown in the picture on the back of the motherboard

3 Install the motherboard on the upper cover

Note: When installing the motherboard, do not press the LCD cable, CCD cable, or Wlan antenna.

4 Take the screws (C)*2 & (D)*1 to fix the motherboard to the upper cover

5 Take the MULTI card and install it on the upper cover as shown in the picture, and secure it with screw (C)*1


1

model				Process	specific version		Code	production date	File No		Site (small)	Page (small)	Site (large)	Page (large)
NS7xx		Combined with left Hinge		Establish	9	Reference 1	1		IE-2525	2021.03.24	9	2-2/16	18	1-1/31
B O M	NO.	Description	Parts Number	QTY 2	Torque	Remark quality	Focus/notes: Tools/consumables:				1. Static electricity bracelet 3. cm 2. Electric screwdriver			
	A screw		6-35-82125-6RA		2.5±0.2		1. You need to wear an electrostatic bracelet							
							during operation 2. The hanging height of the fixture (i.e.: the height of the pallet y the lowest point of the fixture) y3							
							3. Lock the screws in order, and be careful not to slip or miss the lock.							
							This site has 2 pages in total, this is page 2							

Hold

do

explain



- 1 Combine the left Hinge and secure the left Hinge with screws (A)*2 (the one with a triangle symbol on the body)
- Note: The upper cover screw holes and Hinge screw holes must be aligned
- 2 Plug the CCD cable into the motherboard interface
3. As shown in the figure, arrange the small battery cable through the slot 1-hook 1, remove the COMS battery backing tape and stick it in the battery slot.

bright

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

	model			Process-specific version			Code production date	File No			Site (small) Page (small) Site (large) Page (large)
	NS7xx	Plug in the USB cable			Establish	10	Reference 1	1	IE-2525	2021.03.24	102-1/16191-1/31
BOM	NO.	Description A	Parts Number	Q'TY 1	Torque	Remark quality	points/notes: 1. Wear an electrostatic bracelet during work		Tools/Supplies: 1. Static electricity bracelet		
	USB1 TO MB cable 6-43-NS700-031/-1										
This site has 2 pages in total, this is page 1											
Hold do explain bright	1. Take the USB cable (A) and plug it into the MB interface. Tear off the mylar release paper to fix the cable on the motherboard. 2. Tear off the adhesive on the bottom of the USB cable, stick it on the upper cover, insert the USB cable into the small card interface, and remove the mylar release paper from the cable to fix the cable on the small card.										

model		Process	specific version		Code production date	File No		Site (small)	Page (small)	Site (large)	Page (large)
NS7xx	Plug in the USB cable	Establish	10	Reference 1	1	IE-2525	2021.03.24	10	2-2/16	20	1-1/31

B O M	NO.	Description A USB2	Parts Number	Q'TY 1	Torque	Remark quality points	Tools/Supplies: 1. Static electricity bracelet
		TO MB cable 6-43-NS700-021/1 B Click cable 6-43-NS500-010/-1					
				1			

This site has 2 pages in total, this is page 2

Hold

do

explain

bright

Plug the Click cable into the TP interface

Peel off the adhesive tape and stick it on the top cover

Plug the Click cable into the MB interface

Plug the USB cable into the motherboard interface

When attaching the USB cable, do not press it Mylar

Plug the USB cable into the mini card

Peel off the adhesive tape and stick it on the top cover

1. Take the USB cable (A) and plug it into the MB interface. Remove the mylar adhesive on the cable to fix it to the motherboard.

2. Tear off the adhesive on the bottom of the USB cable, stick it on the upper cover, insert the USB cable into the small card interface, and remove the mylar adhesive on the cable to fix the cable on the small card.

3. Open the interface baffle on the T/P, insert the Click cable (A) with the word CK on the interface, snap the baffle to fix the cable, peel off the adhesive at the bottom of the Click cable, and stick it to the upper cover

4 Plug the Click cable into the MB interface

KAPOK Standard Operation PROCEDURE Operation Instructions Operation Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model	Process Type Station Type				Version	Code production date	File No		Site (small) Page (small) Site (large) Page (large)	
NS7xx	FAN + HEATSINK			Establish	11	Reference 1	1	IE-2525	2021.03.24	112-1/16212-1/31

B O M	NO.	Description A	Parts Number	Q'TY 7	Torque	Remark quality points	notes: 1. Wear an electrostatic bracelet during work 2. The hanging height of the jig (ie: the height of the pallet y the lowest point of the jig) y 38 cm 3. Lock the screws in order, and be careful not to slip or miss the lock.	Tools/Supplies: 1. Static electricity bracelet screwdriver
	Screw 6-35-B1120-4RC/-1 B1 FAN + HEATSINK	6-31-NS70N-101 B2 FAN +			1.5±0.2			
	HEATSINK 6-31-NS7PN-100		1			BY S/O		
			1			BY S/O		

This site has 2 pages in total, this is page 1

Hold

do

explain

bright

When handling the fan, do not touch it
Touch the middle of the fan

When installing HEATSINK, do not press it here.
Mylar

1 Install FAN + HEATSINK (Bx) on the top cover as shown in the picture

Note: When installing FAN + HEATSINK, do not press the Mylar & Wlan antenna & CCD cable shown in the picture.

2 Fasten the HEATSINK screws (A)*7 in the order shown in the figure

1

KAPOK Standard Operation PROCEDURE Operation Instructions Operation Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model	Process Type Station Type			Version	Code production date	File No		Site (small) Page (small)	Site (large)	Page (large)	
NS7xx	rational line	Establish	11	Reference 1	1	IE-2525	2021.03.24	11	2-2/16	21	2-2/31

B O M	NO.	Description	Parts Number	Q'TY	Torque	Remark quality points/notes: 1. Wear an electrostatic bracelet during work	Tools/Supplies: 1. Static electricity bracelet

This site has 2 pages in total, this is page 2

Hold

do

explain

bright

1. Tear off the Mylar release paper that comes with the incoming material, as shown in the figure to fix the Wlan antenna & CCD cable

Note: The Mylar that comes with the incoming materials should not be attached to the Wlan card slot.

2 Plug the FAN cable into the position shown on the motherboard

3. Tear off the Mylar release paper that comes with the incoming material to fix the FAN cable & Wlan antenna.

1

KAPOK Standard Operation PROCEDURE Operation Instructions Operation Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26



model		Process Type Station Type				Version	Code production date	File No		Site (small) Page	(small) Site (large)	Page (large)	
NS7xx		Manage LCD cables		Establish	12	Reference 1	1	IE-2525	2021.03.24	12	2-1/16	22	1-1/31
B O M	NO.	Description A	Parts Number	Q'TY 2	Torque	Remark	quality points/notes: 1. Wear an electrostatic bracelet during work			Tools/Supplies: 1. Static electricity bracelet			
	Acetate cloth		6-47-00190-209										
							This site has 2 pages in total, this is page 1						

Hold

do

explain

bright



1. As shown in the figure, pass the LCD cable through hook 1-hook 2, and insert the LCD cable into the motherboard interface.

2 As shown in the picture, attach acetate acid cloth (A)2 to the position shown in the upper cover

1


Write write:Song Xingxing

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model		Process	specific version		Code production date	File No		Site (small)	Page (small)	Site (large)	Page (large)
NS7xx	Flash motherboard & install SPK	Establish	13	Reference 1	1	IE-2525	2021.03.24	12	2-2/16	23	1-1/31
B O M	NO.	Description A1	Parts Number	Q'TY 1 1	Torque	Remark quality	focus/notes: 1. Wear an electrostatic bracelet during work	Tools/Supplies: 1. Static electricity bracelet 2. Brushing the gun 3. Computer			
	SPK-R A2	SPK-R A3	6-23-5N130-0R2-1	1		BY S/O 1.					
	SPK-R B1	SPK-L B2	6-23-5NS5P-0R0			BY S/O BY					
	SPK-L B3	SPK-L	6-23-5NS5A-0R0			S/O BY S/					
			6-23-5NS50-0L1	1		O					
			6-23-5NS5P-0L0	1		BY S/O					
			6-23-5NS5A-0L0	1		BY S/O					

This site has 2 pages in total, this is page 1




- 1 Take SPK-L (Bx), align it with the positioning post, and install it at the position shown in the upper cover
- 2 Take the SPK-R and align it with the positioning post and install it at the position shown in the upper cover.
- 3 Plug the SPK-R (Ax) cable into the motherboard interface

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model				Process station type		Version		Code production date		File No		Site (small) Page (small) Site (large) Page (large)			
NS7xx		Install Wlan card		Establish		12		Reference 1		IE-2525		2021.03.24		133-1/16241-1/31	
B O M	NO.	Description	Parts Number	QTY 1 1	Torque	Remark quality focus/notes:						Tools/Supplies:			
	A1 WLAN card		6-88-N15CF-4210	1		BY S/O 1. Wear an electrostatic bracelet during work 1. Electrostatic bracelet									
	A2 WLAN card		6-88-NV40F-4210			BY S/O 2. The hanging height of the jig (ie: the height of the pallet y the lowest point of the jig) y 38 cm 2. Electric screwdriver									
	A3 WLAN card		6-88-N24GF-4200			BY S/O 3. Lock the screws in order, and be careful not to slip or miss the lock.									
	A4 WLAN card		6-88-X17KF-4210	1		BY S/O									
	B screw		6-35-Z9120-3R2	1	1.5±0.2										
C	Mylar	6-40-M55J2-030	1												
												This site has 2 pages in total, this is page 2			

Hold



Wlan天線對應Wlan卡接口區分方式			
天線	Wlan-1天線	Wlan-2天線	Wlan-3天線
Wlan卡 PCB板上接 口標示	"M"	"A"	
	"A"	"B"	
	"1"	"2"	"3"

注意：Wlan卡接口標示需按PCB板上的印刷字樣為主來區分！！！

Antenna distinction method			
Antenna Type	線材顏色	套筒顏色	
Wlan-1	黑色	透明	
Wlan-2	灰色	透明	
Wlan-2	黑色	白色	
Wlan-3	白色	透明	

The following table is for reference only, the actual product is based on the actual product.

Wlan卡	Wlan卡	Wlan卡	Wlan卡	Wlan卡	Wlan卡	A
3	1	1	1	M	O	
1	2	2	2	A	O	B
2						
Wlan卡	Wlan卡	Wlan卡	Wlan卡	Wlan卡	Wlan卡	B
3	1	1	1	A	O	
1	2	2	2	M	O	A
2						

The following steps 1, 2, 3, and 4 are for when the Wlan card is issued:

1 Take the WLAN card (A)


NOTE: For Customer Consign Wlan, Apply "CONSIGN" sticker

2 Install the Wlan card on the interface, take the screw (B)* and lock it on the stud

Insert Wlan-1&wlan-2 antennas on the wlan card. 3 Notes:

1. See the picture above for the wiring sequence of the Wlan card. 2. See picture 4 for the color distinction of the Wlan antenna. Arrange the Wlan antenna as shown in the picture, and attach Mylar (C) to the Wlan antenna and Wlan antenna head

1




The following steps 5 and 6 are for when the Wlan card is not available:

5 Take the screw (B)* and lock it on the stud

6. As shown in the figure, connect the Wlan antenna to the Mylar (C) position to fix the Wlan antenna at the position shown on the motherboard. Write: Song Xingxing

2

This site has 2 pages in total, this is page 2



The following steps 1, 2, 3, and 4 are for when the Wlan card is issued:

1 Take the WLAN card (A)

NOTE: For Customer Consign Wlan . Apply "CONSIGN" sticker


2 Install the Wlan card on the interface, take the screw (B)* and lock it on the stud

Insert Wlan-1&Wlan-2 antennas on the wlan card. 3 Notes:

1. See the picture above for the wiring sequence of the Wlan

card. 2. See picture 4 for the color distinction of

the Wlan antenna. Arrange the Wlan antenna as shown in the picture, and attach Mylar (C) to the Wlan antenna and Wlan antenna head



The following steps 5 and 6 are for when the Wlan card is not available:

5 Take the screw (B)* and lock it on the stud

6. As shown in the figure, connect the Wlan antenna to the Mylar (C) position to fix the Wlan antenna at the position shown on the motherboard. Write: Song Xingxing

Review check:Qian Lin

Write write:Song Xingxing

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model				Process	specific version		Code production date	File No		Site (small)	Page (small)	Site (large)	Page (large)	
NS7xx		Flash motherboard & install RAM		Establish	13	Reference 1	1	IE-2525		2021.03.24	13	3-2/16	25	1-1/31
B O M	NO.	Description	Parts Number	Q'TY 1	Torque	Remark quality	points/notes: 1. Wear an electrostatic bracelet during work			Tools/Supplies: 1. Static electricity bracelet 2. Brushing the gun 3. Computer				
	A RAM		BY SO											



This site has 2 pages in total, this is page 1

Hold

do

explain

bright





- 1As shown in the figure, arrange the SPK-L cable through hook 1, arrange the excess cable in the position shown in the figure, and insert the SPK-L cable into the motherboard interface.
 2. Flash the machine & motherboard barcode into the system
 3. Paste the barcode on the motherboard. The font direction of the barcode is consistent with the direction of the mainboard material number of the laser engraving strip on the motherboard.
 4. Install RAM (A)----(Install the right card slot RAM1 first, then install the left card slot RAM2)
- When 5 needles come out of the RAM: stick a monthly mark on the RAM ----The direction of the monthly mark is consistent with the font direction of the incoming material label
6. For customers to Consign RAM, put a "Consign sticker" on the RAM to replace the monthly label.

Review check:Qian Lin

Write write:Song Xingxing




KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model				Process station type		Version		Code production date		File No		Site (small) Page (small) Site (large) Page (large)													
NS7xx		Install M.2 SSD		Establish		13		Reference 1		1		IE-2525		2021.03.24		13		3-3/16		26		1-1/31			
B O M	NO.	Description	Parts Number	Q'TY 1	Torque	Remark	Quality Focus/Notes: Tools/Supplies:					This site has 2 pages in total, this is page 2													
	The SSD		By S/O	or 2 1		W/ SSD	1. You need to wear an electrostatic bracelet												1. Static electricity bracelet						
	B SSD screw		6-35-Z9120-3R2	or 2 1	1.5±0.2		during operation 2. The hanging height of the fixture (i.e.: the height of the pallet y the lowest point of the fixture) y38 cm 2. Electric screwdriver																		
	C Thermal Pad		6-48-L1402-010	or 2			3. Lock the screws in order, and be careful not to slip or miss the lock.																		
Hold																									
do	 When using 1 SSD (except SATA SSD): 1 Attach THERMAL PAD (C2) to the position shown in the picture in slot 2 of the motherboard 2. Take the SSD card (A2) and put the monthly label on the SSD card. Note: For the customer's Consign SSD card, put the "Consign sticker" instead of the monthly label. 3Insert the SSD card into the card slot 2 interface and secure it with the screw (B2) When targeting 1 SATA SSD: 4. Attach THERMAL PAD (C1) to position 5 in the card slot 1 of the motherboard as shown in the figure. Take the SSD card (A1) and affix the monthly label on the SSD card. Note: For the customer's Consign SSD card, affix the "Consign sticker" to replace the monthly label 6. Insert the SSD Card into the card slot 1 interface, and take out the screw (B1) to lock it. Note: For W/SSD*2, the SSD for the OS is installed in the GEN4*4 card slot/If the highest specification of the model is GEN3*4 , then install it in the GEN3*4 card slot Note: SATA SSD can obtain the word SATA in the BOM or first article description based on the material number.  Monthly label/consign sticker When targeting 2 SSDs: 7 Paste THERMAL PAD (C)*2 in the white frame of the motherboard 8. Take 2 SSD cards (A) and put the monthly label on the SSD card. Note: For customers to Consign SSD cards, put the "Consign sticker" to replace the monthly label. 9 Insert the SSD card into the interface and secure it with screws (B)*2																								
explain																									
bright																									

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model				Process-specific version				Code production date		File No		Site (small) Page (small) Site (large) Page (large)											
NS7xx		Install battery		Establish		14		Reference 1		1		IE-2525		2021.03.24		14		3-1/16		27		2-1/31	
B O M	NO.	Description	Parts Number	Q'TY 1	Torque	Remark quality focus/notes: 1. Wear an electrostatic bracelet during operation 2. Pressing time: 10s 3. Fixture pressure 0.3-0.4MPa		Tools/Supplies: 1. Static electricity bracelet 2.Battery assembly jig: NS70MU-YH04-1003-01															
	A battery		6-87-L140S-32B02/-32B03																				
	This page is for 36W battery operations										This site has 3 pages in total, this is page 1												
Hold	  																						
do																							
explain																							
bright	1. Remove the release paper at locations 1, 2, 3, and 4 of the zipper shown in the picture. 2 Plug the battery cable into the motherboard interface 3. Install the battery (A) on the left side of the upper cover as shown in the picture. 4. Take the machine and place it in the jig as shown in the figure, start the jig to press the battery, the pressing time is: 10s 5. After pressing is completed, take out the machine																						

1

Review check:Qian Lin

Write write:Song Xingxing




KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model		Process	specific version		Code production date	File No		Site (small)	Page (small)	Site (large)	Page (large)
NS7xx	Install battery	Establish	14	Reference 1	1	IE-2525	2021.03.24	14	3-2/16	27	2-2/31

B O M	NO.	Description	Parts Number	Q'TY 1	Torque	Remark quality focus/notes:	Tools/Supplies:
	A battery		6-87-NS70S-72B00/-72B01			BY S/O 1. Wear an electrostatic bracelet during operation 2. Pressing time: 10s 3. Fixture pressure 0.3-0.4MPa	1. Static electricity bracelet 2. Battery assembly jig: NS70MU-YH04-1003-01
	This page is for 73W battery operations						This site has 3 pages in total, this is page 2

Hold



do

explain

1. Peel off the adhesive tape 1, 2, 3 and 4 shown in the picture.
- 2 Plug the battery cable into the motherboard interface
3. Install the battery (A) on the left side of the upper cover as shown in the picture.
4. Take the machine and place it in the jig as shown in the figure, start the jig to press the battery, the pressing time is: 10s
5. After pressing is completed, take out the machine

bright

model		Version					Code production date	File No		Site (small)	Page (small)	Site (large)	Page (large)
NS7xx		Fixture lower case		Establish	14	Reference 1	1	IE-2525	2021.03.24	14	3-3/16	28	1-1/31
	NO.	Description	A Jig	Parts Number	Q'TY 1	Torque	Remark	quality	ocus/notes: Tools/consumables: 1. Wear an electrostatic bracelet during work 1. Electrostatic bracelet 2. The hanging height of the jig (that is: the height of the pallet y the lowest point of the jig) y 38 cm 2. Electric screwdriver 3. Lock the screws in order, and be careful not to slip or miss the lock.				
	lower cover	B Jig lower	6-39-xxxxxx										
	cover screws		6-35-B6120-5R0	0.4	2.0±0.1								
									This site has 3 pages in total, this is page 3				



Hold

do

explain

bright



KAPOK Standard Operation PROCEDURE Operation Instructions Job Name											
model			Process type	stand farewell	Version	Code production date	File No		Site (small) Page (small)	Site (large) Page (large)	
NS7xx		K/B processing		Establish	15	Reference 1	1	IE-2525	2021.03.24	15	2-1/16
B O M	NO.	Description	Parts Number	Q'TY 1 1	Torque	Remark quality points/notes: 1. Wear an electrostatic bracelet during work			Tools/Supplies: 1. Static electricity bracelet		
	AK/BB Mylar		BY SO								
			6-40-NS702-021		For non-illuminated keyboards						
This site has 2 pages in total, this is page 1											
Hold	 Plug the LID cable into the motherboard interface Plug the K/B cable into the motherboard interface For non-illuminated keyboards Align the 5 holes and attach MYLAR (B)  C										
do											
explain	1 Turn over the machine 2 Plug the LID cable & K/B cable into the motherboard interface The following steps are for working with a non-illuminated keyboard 5 As shown in the picture, paste K/B Mylar(B) in the K/B frame of the upper cover Be careful not to climb walls when attaching K/B Mylar										
bright											

KAPOK Standard Operation PROCEDURE Operation Instruction Operation Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model	Process Station Specific Version							Code production date	File No		Site (small) Page (small)	Site (large) Page (large)		
NS7xx	Install K/B				Establish	15	Reference 1	1	IE-2525	2021.03.24	15	2-2/16	30	1-1/31

B O M	NO.	Description	Parts Number	Q'TY	Torque	Remark quality points/notes: 1. Wear an electrostatic bracelet during work	Tools/Supplies: 1. Static electricity bracelet



This site has 2 pages in total, this is page 2

Hold

do

explain

bright



The following steps 1, 2, and 3 work when K/B appears

1 Take K/B and paste the barcode on K/B

Note that the direction of the barcode is consistent with the font direction of the incoming material label. The barcode cannot cover the incoming material label.

2 Plug the keyboard cable into the motherboard

Pay attention to plug in the large cable first, then the small cable——when targeting the illuminated keyboard


3. Snap the keyboard onto the upper cover and make sure the hook is fully engaged.


Note 1. First snap the bottom edge of the keyboard into the upper cover, then snap it into both sides and the top

2. Before engaging the keyboard, check that the K/B cable is not wrinkled

KAPOK Standard Operation PROCEDURE Operation Instructions Job Name

The limited period of the SOP on this page is: 2023/7/26~~~2023/10/26

model					Process	specific version			Code production date	File No			Site (small)	Page (small)	Site (large)	Page (large)
NS7xx		General inspection			Establish	16	Reference 1		1	IE-2525	2021.03.24		16	2-1/16	31	2-1/31
B O M	NO.	Description	Parts Number	Q'TY	Torque	Remark	quality	oints/notes: 1. Wear an electrostatic bracelet during work				Tools/Supplies: 1. Static electricity bracelet				
								This site has 2 pages in total, this is page 1								
Hold																
do																
explain																
bright																
1. Check that the screws on the lower cover of the fixture are not leaked or scratched.																
2 Check that the battery must be locked																
3 Check that there is no gap in the lower part of the machine																
4. Check that there are no gaps or scratches on the hinge side of the machine.																
5 Check the USB interface: the inside of the USB 2.0 interface is black, and the inside of the USB 3.0 interface is blue.																

model					Process	specific version			Code production date	File No			Site (small)	Page (small)	Site (large)	Page (large)
NS7xx		General inspection			Establish	16	Reference 1		1	IE-2525	2021.03.24		16	2-2/16	31	2-2/31
B O M	NO.	Description	Parts Number	Q'TY	Torque	Remark quality points/notes: 1. Wear an electrostatic bracelet during operation 2. Increase the illumination value: 800~1200lm/y						Tools/Supplies: 1. Static electricity bracelet 2. Thick and thin rules				
												This site has 2 pages in total, this is page 2				
Hold	one  1. Plug in the AC and wait for 6 seconds before pressing the AC button to turn on the phone. button to turn on the computer, unplug the AC after turning on the computer, and check first Check whether the startup screen is complete and Hinge rotation is No interference, etc. (Reference 1) - Need to be plugged in when starting up source line to activate two  2. Secondly check the power button and APK button Is the key flexible for shutting down and turning on and off the machine? The keys must not be inactive and the printing must be complete. No missing prints (reference 2) three  3. Tear off the protective film again, and the front frame There should be no scratches/dirty/residual glue, etc. (Reference 3) Four  4. Check the T/P button space on the upper cover again The gapstep difference cannot exceed the standard and must have merit Yes, no scratches/dirty/residual glue Wait (Reference 4) five  5. Check again that the back cover is not scratched /Dirty/residual glue, if printing Logo needs to be finished Complete, no missing prints, etc. (Reference 5) six  6. Check the front, rear and sides again. There are scratches/dirty/residual glue, four major items No gaps/breaks/impacts after assembly Can exceed the standard (reference 6) seven  7. Check again that there are no scratches on the left and right sides. Damage/dirty/residual glue, after the four major parts are combined The gap/discrepancy cannot exceed the standard (Reference 7) eight  8. Shake the machine again and the screws cannot be heard. Encountering noises inside the machine (Reference 8) Nine  9. With the opening upward, stand the machine 90 degrees, thick Thin gauge inspection, GAPy5mm is OK (reference Nine) ten  10. If K/B does not come out, check K/B Lock is complete (Reference 10) eleven  11. Finally check whether the process card information is correct correct															
do																
explain																
bright	Note: 1: The gap between the LCD and the front cover must not exceed 0.8mm below, and no single point protrudes on both sides; 2: For defective machines, record the defective phenomena in the process card Test the AUTO LOCK function (see Figure 9 for details) Note: With the opening upward, stand the machine 90 degrees and check with the thickness gauge. GAPy5mm is OK. 1. For new models after 1500PCS, first piece measurement 2. For new models within 1500 PCS, first make a visual inspection. If the visual inspection GAP is too large, use a thickness gauge to measure it.															

1

Note: 1: The gap between the LCD and the front cover must not exceed 0.8mm below, and no single point protrudes on both sides;
2: For defective machines, record the defective phenomena in the process card

Test the AUTO LOCK function (see Figure 9 for details)
Note: With the opening upward, stand the machine 90 degrees and check with the thickness gauge. GAPy5mm is OK.
1. For new models after 1500PCS, first piece measurement
2. For new models within 1500 PCS, first make a visual inspection. If the visual inspection GAP is too large, use a thickness gauge to measure it.